Clood Damage Inventory

PRINCE GEORGE'S COUNTY



TO CONTRACTOR

MARYLAND

July 1981



Environmental Planning Division
THE MARYLAND-NATIONAL CAPITAL PARK AND PLANNING COMMISSION

FLOOD DAMAGE INVENTORY

PRINCE GEORGE'S COUNTY MARYLAND

JULY 1981

Environmental Planning Division
The Maryland-National Capital Park and Planning Commission

TC 224.M3 F66 1881

FLOOD DAMAGE INVENTORY

PRINCE GEORGE'S COUNTY MARYLAND

Prepared by:

The Environmental Planning Division
The Maryland-National Capital Park and Planning Commission
14741 Governor Oden Bowie Drive
Upper Marlboro, Maryland 20772

for:

The Maryland Department of Natural Resources
Tidewater Administration
Coastal Resources Division

and

Water Resources Administration Tawes State Office Building Annapolis, Maryland 21401

THE MARYLAND-NATIONAL CAPITAL PARK AND PLANNING COMMISSION

PRINCE GEORGE'S COUNTY PLANNING BOARD

CHARLES A. DUKES, JR., Chairman EDWIN H. BROWN JOHN W. CHURCHILL JOHN H. CUMBERLAND ANN C. SHOCH

MONTGOMERY COUNTY PLANNING BOARD

NORMAN L. CHRISTELLER, Chairman MABLE GRANKE JUDITH B. HEIMANN BETTY ANN KRAHNKE SHELDON P. SCHUMAN

DEPARTMENT HEADS

THOMAS H. COUNTEE, JR. Executive Director

A. EDWARD NAVARRE Secretary-Treasurer

ARTHUR S. DREA, JR. General Counsel

JOHN F. DOWNS, JR.
Planning Director
Prince George's County

RICHARD E. TUSTIAN Planning Director Montgomery County

HUGH B. ROBEY
Director of Parks and Recreation
Prince George's County

STANTON G. ERNST Director of Parks Montgomery County

ROBERT D. REED Community Relations Officer Prince George's County

JOHN HOOVER Community Relations Officer Montgomery County

Prince George's County Regional Office County Administration Building 14741 Governor Oden Bowie Drive Upper Marlboro, Maryland 20772 Montgomery County Regional Office 8787 Georgia Avenue Silver Spring, Maryland 20907

ACKNOWLEDGEMENTS

We would like to acknowledge the significant contributions made by those participating in the preparation of the Flood Damage Inventory.

ENVIRONMENTAL PLANNING DIVISION

Stan Udhiri, Chief Dominic J. Motta, Planner III* Wendell E. John, Planner I* Frances J. Guertin, Secretary III

PLANNING DEPARTMENT ASSISTANCE

Lauren Arth, Word Processing Operator IV Charles Colella, Drafting Technician III William Limpert, Water Resources Planning Assistant Benetta Yeatman, Drafting Technician II

MARYLAND WATER RESOURCES ADMINISTRATION STAFF ASSISTANCE

Robert B. Dannecker, Chief, Flood Management Division Mary Lou Soscia, Natural Resources Planner

*Primarily responsible for the report.

Contents

				Page		
SUMM	ARY .			1		
1.0	Purp	ose of	Study	2		
	1.1 1.2 1.3 1.4	Coordi	round rization ination dology	2 2 2 3		
2.0	County Description					
	2.1	Locati Major	ion and Physiographic Description	3 5		
3.0	Flooding Problems					
	3.1 3.2	County Potoma	ywide Discussion ac River Sub-Watershed	5 9		
		3.21 3.22 3.23 3.24 3.25 3.26 3.27 3.28	Anacostia River Beaverdam Creek Oxon Run Henson Creek Piscataway Creek Tinkers Creek Mattawoman Creek Lower Potomac	13 14 15 15		
·	3.3	Patux	ent River Sub-Watersheds	18		
		3.31 3.32 3.33 3.34 3.35 3.36 3.37	Upper Patuxent Horsepen Branch Western Branch Collington Branch Charles Branch Middle Patuxent Lower Patuxent	18 20 23 23		
4.0	Refe	erences		27		
Appe	ndix	A - Sa	mple Letter of Notification	A-1		
Арре	endix		ghwater Elevation of Selected Prince George's unty Bridges	B - 1		
Appe	endix	C - Se	lected Comments on Floodprone Properties	C-1		
Anne	endix	D - In	ventory of Floodprone Structures	n_1		

	<u>Tables</u>	Page
1.	Structures Impacted by the 100-Year Flood Prince George's County	7
	<u>Figures</u>	
1.	Vicinity Map	4
2.	Major Watersheds	6
3.	Percentage of Flood-prone Structures by Watershed	8
4.	Flood-prone Structures - Anacostia River and Beaverdam Creek Watersheds	10
5.	Percentage of Flood-prone Structures - Anacostia Sub-Watershed	11
6.	Flood-prone Structures - Oxon Run/Watts Branch and Henson Creek Watersheds	14
7.	Flood-prone Structures - Piscataway Creek and Tinkers Creek Watersheds	16
8.	Flood-prone Structures - Upper Patuxent	19
9.	Flood-prone Structures - Western Branch and Collington Branch Watersheds	21
10.	Percentage of Flood-prone Structures - Western Branch Sub-Watersheds	22
11.	Flood-prone Structures - Middle Patuxent	25
12.	Flood-prone Structures - Lower Patuxent	-26

.

Summary

This report contains an inventory and aerial cataloging of flood-prone properties in Prince George's County. On the basis of this study, a total of 1,676 structures comprising 1,260 residential, 273 commercial and 143 other structures are wholly or partially in the floodplain.

This inventory will serve as a pilot project for possible replication Statewide, to allow for assessment of the potential magnitude and frequency of flood damage in the State. The information contained in such an inventory will also help the State assess mitigation alternatives and priorities for governmental action.

1.0 Purpose of Study

The purpose of this study is to inventory and catalogue floodprone properties in Prince George's County. This information will help the State administer the Flood Management Grant Program and serve as a vehicle for notifying the owners of floodprone properties of floodprone hazards, and the relief available through federally subsidized flood insurance.

1.1 Background

Although large amounts of public funds have been spent in Maryland to mitigate damage from periodic flooding, no concerted effort has been made state-wide to collect, assess or distribute information on flood damages. It is particularly discouraging that no comprehensive effort has been made to notify the owners of potentially floodprone structures of the availability of federally subsidized flood insurance. In order to address this situation, the Environmental Planning Division of the Prince George's County Planning Board, in cooperation with the Maryland Water Resources Administration and the Coastal Zone Management Program has undertaken an inventory of flooding problems within the County. This "Flood Damage Data Inventory" will serve as a pilot project for possible replication statewide. The information gathered will result in an aerial cataloging and filing system for storage and retrieval of flood damage information which will allow assessment of flood damaged areas including history, average annual damages, mitigation alternatives and priority for governmental action.

1.2 Authorization

This study was prepared in accordance with Contract No. C4-78-440(81) between the State of Maryland, Department of Natural Resources, Tidewater Administration, Coastal Resources Division and the Maryland-National Capital Park and Planning Commission - representing Prince George's County.

1.3 Coordination

Interviews were conducted with staff of the Washington Suburban Sanitary Commission and the Department of Public Works. Information on flooding due to stream overflows and inadequate drainage was sought from residents of the watersheds. A thorough review of available information on flooding and inadequate drainage problems was also conducted to assist in the identification of floodprone properties. Fortunately, a considerable amount of information on flooding problems exists for Prince George's County including U.S. Army Corp of Engineers Floodplain Information Reports. Although some of these studies were performed over ten years ago and are in need of updating, they do provide useful historical flood information. In addition, some information is readily available from Stormwater Management Studies and Comprehensive Watershed Management Plans being prepared by the County's Storm Water Management Technical Group. Of particu-

lar value was the report on Flooding prepared by the Prince George's County Task Force after the occurrence of Hurricane Agnes in June 1972.

1.4 Methodology

In order to manage the flood data by geographic zones, the boundaries of major watersheds were delineated. Within each watershed, the best available floodplain delineation was used in conjunction with recent aerial photography and County Premise Address Maps to identify the location and address of floodprone properties. Since one of the principal purposes of the study is to notify property owners of the floodproness of their structures, a conservative approach was used whereby all borderline structures were included in this initial inventory.

2.0 County Description

2.1 Location and Physiographic Description


Prince George's County is a 485 square mile jurisdiction which lies directly to the east and borders on Washington, D.C. The Patuxent River forms the northern and eastern boundaries of the County; while the Potomac River, District of Columbia and Montgomery County form the western boundary. Charles County lies directly to the south. The location of the County is shown in Figure 1.

The physical characteristics of the County are defined primarily from the underlying geology as altered by climatic and hydrologic conditions. Except for a small area along the Montgomery County boundary, Prince George's County lies almost entirely within the physiographic province known as the Atlantic Coastal Plain. The geology of the Coastal Plain consists of unconsolidated sediments of sand, silt, clay and gravel deposited upon the underlying crystalline rocks. The depth of these sediments decrease from east to west, thinning out in a wedgelike manner near the border between Montgomery and Prince George's Counties.

The northern part of the Coastal Plain in Prince George's County is gently rolling and has broad valleys. The remainder is a partly dissected low-plateau that extends into Charles County. Near the Patuxent and Potomac Rivers this plateau is cut by V-shaped valleys that have short, steep slopes. Elevations range from sea level along the lower reaches of the major rivers to over 400 feet in the northernmost portion of the County near the Rocky Gorge Reservoir.

All the major streams in the County are normally sluggish and most are in broad valleys. Because coastal plain soils are highly erodible, siltation is a major problem. The wide valleys with extensive floodplains also lead to considerable flooding problems during major storm events.

FIGURE 1. LOCATION OF PRINCE GEORGE'S COUNTY, MARYLAND



2.2 Major Watersheds

Prince George's County is divided almost equally between two major river basins, the Potomac River which occupies the western half of the County and the Patuxent River which occupies the eastern half. The Potomac River Basin is largely urbanized and contains most of the existing residential, commercial and industrial development in Prince George's County. The Patuxent River, on the other hand, is still mostly rural and is dominated by agricultural land uses.

For the purpose of watershed planning and to facilitate a discussion of flooding problems, each River Basin has been divided into major subwatersheds as follows:

Potomac River Basin

Anacostia River
Beaverdam Creek
Oxon Run
Henson Creek
Piscataway Creek
Tinkers Creek
Lower Potomac

Patuxent River Basin

Upper Patuxent Horsepen Branch Western Branch Collington Branch Charles Branch Middle Patuxent Lower-Patuxent

The location of these sub-watersheds is identified on Figure 2. A complete description of each sub-watershed is included in Section 3.0 under flooding problems.

3.0 Flooding Problems

3.1 Countywide Discussion

As land uses in Prince George's County have changed from rural agricultural and forest uses to urban and suburban subdivisions, shopping centers and employment parks, the impact of flooding has gradually increased. Although floodplain encroachments have been minimized in recent years by strong local regulation, occasional conflicts still occur due to changes in stream hydrology and hydraulics and changes in the definition of the regulated floodplain. The effect of changing land uses on flood damage was brought into sharp perspective on June 22, 1972, when tropical storm Agnes struck and left in its wake damage and disruption unequalled by previous storms. Agnes caused more than \$10 million in damage in Prince George's County and resulted in a heightened appreciation of the power of floodwaters.

Because most of the development in Prince George's County has occurred in the Potomac River Basin near Washington, D.C. the majority of the flooding problems have also occurred in this basin, particularly in the Anacostia sub-watershed. Our inventory has identified a total of 1,646 floodprone structures including 1,209 in the Potomac River Basin and 439 structures in the Patuxent River Basin. While 86% of the floodprone residential structures are located in the Potomac Basin only 48% of the flood-





Table 1
Structures Impacted by 100-Year Flood

		Structures		
Watershed	Total	Residential	Commercial	0ther
				• •
Anacostia	811	721	78	12
Beaver Dam Creek	97	65	31	1
Oxon Run	9	9	•	-
Henson Creek	203	188	11	4
Piscataway Creek	73	71	1	1
Tinkers Creek	44*	34*	9	1
Lower Potomac	-	-	•	-
Total Potomac	1,239	1,088	130	19
Upper Patuxent	79	30	49	-
Horsepen Branch	_	-	-	-
Western Branch	324	111	93	120
Collington Branch	16	11	Ī	4
Charles Branch	_	-	_	_
Middle Patuxent	6	6	-	_
Lower Patuxent	14	14		
Total Patuxent	439	172	143	124
Total County	1,676	1,260	273	143

^{*} Includes 30 trailer homes

PERCENTAGE OF FLOODPRONE STRUCTURES MAJOR WATERSHEDS



prone commercial structures are located there. The majority of the flood-prone commercial structures are located in the City of Laurel in the Upper Patuxent sub-watershed. Table I identifies the number of structures by type and watershed impacted by the 100 year flood in Prince George's County. The percentage of flood-prone structures by watershed is diagrammed in Figure 3.

3.2 Potomac River Sub-Watersheds

3.21 Anacostia River Watershed


The Anacostia River Watershed is 120 square miles with 68 square miles of the lower portion within Prince George's County and the remainder in Montgomery County. The entire watershed has been designated a State Scenic River and is currently being studied under this program. The two main tributaries of the Anacostia are Northeast and Northwest Branches. These tributaries originate in the Piedmont in Montgomery County, cross the fall line onto the Coastal Plain and merge into a tidal estuary near the D.C. line. Land use within the watershed is varied with the lower reaches inside the Capital Beltway heavily developed with a mixture of residential, commercial, industrial and institutional uses. Outside the Beltway, the watershed is less developed with the Beltsville Agricultural Research Center making up a large area of agricultural and forestry uses. An extensive stream valley park system provides recreational and open space benefits to large numbers of County citizens.

Because much of the Anacostia River Watershed is heavily developed, numerous flooding problems exist. A total of 811 structures have been identified within the watershed including 721 residential structures, 78 commercial and 12 other structures. Figure 4 identifies the approximate location of these flood-prone structures. Six major tributaries contribute to the flow of the Anacostia River. These are: Northwest Branch, Sligo Creek, Northeast Branch, Indian Creek, Paint Branch and Little Paint Branch. The relative severity of flooding in each of these tributaries is shown in Figure 5.


Northwest Branch and its tributary Sligo Creek were probably the hardest hit streams in the watershed during the flood resulting from Tropical storm Agnes in June 1972. Damages were particularly severe in the communities of Lewisdale, Riggs Manor and Chillum where over 200 homes were flooded. Other flood-prone areas include the region around the Queens Chapel and Queenstown shopping complex and the Queenstown Apartments. The major floodprone areas in Northeast Branch include Riverdale and East Riverdale. In the Paint Branch and Little Paint Branch watersheds serious flooding occurs in Lakeland, the Cherry Hill Subdivision and areas along Route 1. A significant number of floodprone properties are found along Indian Creek in Beltsville Heights, Greenwood Road, Somerset Avenue, Springhill Lake, Old Branchville Road and Berwyn Heights.

ANACOSTIA RIVER & BEAVERDAM CREEK WATERSHEDS STRUCTURES IMPACTED BY 100 YEAR FLOODPLAIN

FIGURE 4



PERCENTAGE OF FLOODPRONE STRUCTURES ANACOSTIA SUB-WATERSHEDS



In response to the known flooding problems in the Anacostia Watershed. a number of projects have been developed or are planned to alleviate some of the worst flooding problems and prevent an increase in flooding in the future. Many of these projects were initiated by the U.S. Army Corps of Engineers in coordination with the WSSC and include the realignment and excavation of reaches on Sligo Creek, Northwest Branch, Paint Branch, Indian Creek, Northeast Branch and the Anacostia River. Other flood control projects within the watershed include earthen levees, storage ponds, impoundments, reconstructed bridges and pump stations for the conveyance of stormwater. Two major flood control projects are currently included in the WSSC CIP (Capital Improvement Program) for Northwest Branch at Allison Street in Brentwood and for Indian Creek in Beltsville. When these two projects are completed, approximately 236 structures will no longer be impacted by the 100 year flood. Prince George's County plans to initiate a Comprehensive Watershed Management Plan for this watershed in FY 1983 to further address present and future flooding problems.

3.22 Beaverdam Creek Watershed

The Beaverdam Creek Watershed which consists of approximately 16 square miles of land area is adjacent to the District of Columbia and south of the Baltimore-Washington Parkway. Much of the basin is already developed with a considerable number of commercial and industrial establishments. A major highway (Route 50), the Penn Central Railroad, and a Metro Transit line all closely parallel the mainstem of Beaverdam Creek.

Flooding problems occur along the mainstem of Beaverdam Creek and its major tributaries, Cabin Branch and Cattail Branch. The major problems are due to loss of natural storage from floodplain encroachment and increased runoff from major graded, paved and piped or channelized reaches. Loss of conveyance due to obstructions, debris and sedimentation and undersized bridge openings also add to flood stages. Ninety-seven (97) structures were identified by this survey as potentially floodprone, including 65 residential structures and 32 commercial or other structures. Figure 4 identifies the general location of flooding problems in the Beaverdam Creek Watershed. The most serious flooding occurs in the lower portions of the watershed in the north Englewood section of Cheverly, Beaverdam Estates, Beaver Road Industrial Area, Columbia Park and Tuxedo Industrial Area. Flooding also occurs in Palmer Park along Cattail Branch and in Carmody Hills and Cedar Heights along Cabin Branch.

Because the watershed is already heavily developed, the County has been pursuing a site specific approach to manage the increased stormwater flows, instead of developing a Comprehensive Watershed Management Plan. The site specific approach, however, will not alleviate existing flooding conditions. Consideration is therefore being given to initiating a Comprehensive Watershed Management Plan in FY 1983.

3.23 Oxon Run and Watts Branch Watershed

Oxon Run is a 14 square mile watershed. It drains the area inside the Beltway at the southern portion of the Prince George's County that borders the District of Columbia. Approximately 10 square miles of the watershed are located in Prince George's County. The small Watts Branch Watershed which drains from Capitol Heights and Maryland Park towards the District of Columbia, is also included as part of Oxon Run in this inventory. Despite being the most completely developed watershed in Prince George's County with primarily residential land uses, Oxon Run has been one of the more successfully managed urban streams in Prince George's County. Much of the downstream portion of Prince George's County has been protected from intensive development by parkland, cemetery and other open space uses. This has helped to minimize flood damages in the past; however, floodplain encroachment and channelization within the cemeteries may have an adverse impact in the future on properties further downstream.

Nine (9) residential structures have been identified as being prone to flooding from a 100 year storm. These residences are located on Green Valley Drive in Suitland on Oxon Run, and Drum Avenue on Watts Branch. Figure 6 identifies the general location of flood-prone structures in the watershed.


Because Oxon Run is already highly developed and flood damages minor, no comprehensive watershed study has been completed or is scheduled in the near future. The County's watershed management approach will continue to be site specific. New development will be evaluated on an individual basis to minimize the effects of increased flows and corrective projects will be constructed where a need is demonstrated.

3.24 Henson Creek Watershed

Henson Creek is a 25 square mile watershed located in southwest Prince George's County. The creek originates near Andrews Air Force Base and discharges into an embayment on the Potomac River. Considerable residential development, both single- and multi-family, has already occurred in the upper portions of Henson Creek. The remainder of the basin is gradually developing in single-family residential uses. Future industrial development near Andrews AFB and a proposed Metro station will spur additional development in the watershed. Although Henson Creek is relatively small in size in relation to the other major watersheds in the County, it has had more than its share of flooding problems. A total of 191 structures has been identified as flood-prone within the watershed including 176 residential structures, 11 commercial and 4 other structures. Figure 6 identifies the general location of these flood-prone properties. The upper portion of the watershed, which is generally flat, has experienced considerable development, some of which has encroached on the floodplain. The most serious flooding problems in this portion of the watershed have occurred along Woodland Road, Weldon Drive, Keppler Road and Beachcraft Court. The lower portion of Henson Creek has some special flooding problems. Several tributaries including Hunters Mill Branch, originate on old alluvial terraces

FIGURE 6

OXON RUN & HENSON CREEK WATERSHEDS STRUCTURES IMPACTED BY 100 YEAR FLOODPLAIN



along the Potomac River and cut V-shaped valleys with short, steep slopes. These streams generate high flash runoffs and erosion problems which result in sedimentation and flooding conditions when level areas and inadequate culverts are encountered. This problem is particularly severe due to backwater effects at Indian Head Highway. Below Oxon Hill Road, Henson Creek is re-named "Broad Creek" and is a wide flat stream under tidal influence where much of the sediment load from the entire system is deposited.

Past efforts to control flooding within the watershed include several small channelization projects. In particular, a flood channel constructed along the main stem in the vicinity of Woodland Road should help to decrease flooding in this area. The current WSSC CIP includes a project to alleviate the flooding along Weldon Drive. A Comprehensive Watershed Management Plan for the Henson Creek Watershed has been initiated and will be completed during FY 1982. This Plan will address the stormwater management and erosion control problems and will recommend solutions to present and future flooding problems.

3.25 Piscataway Creek Watershed

Piscataway Creek is a 67 square mile watershed located in Southern Prince George's County. Rising on Andrews AFB, the creek flows in a southwesterly direction, discharging into a large embayment on the Potomac. Of its 67 miles of land area, 17 are included in the Tinkers Creek Watershed which will be discussed separately. Much of the watershed remains in rural land uses with scattered residential subdivisions. Most of this development occurs in the north central portion of the basin along Md. Route 5. Because development has not progressed as rapidly as expected, flooding problems have not been severe in this watershed. However, development in the upper portions of the Piscataway Creek Watershed is expected to increase significantly in the future, and could generate more flooding problems in the middle and lower portions of the basin. This survey identified 73 structures which are potentially prone to flooding during the 100 year storm including 71 residential structures 1 commercial structure and 1 other structure. Figure 7 identifies the general location of these structures.

The most serious flooding problems within the watershed are on the lower portion of the mainstem along Livingston Road, Floral Park Road and in the lower portions of Windbrook Subdivision. Further upstream, the Clinton Acres Subdivision is also subject to flooding problems.


In order to address the problems of present and future flooding, a Comprehensive Watershed Management Plan has been initiated for the Piscataway Creek Watershed. This Plan will be completed during FY 1983.

3.26 Tinkers Creek Watershed

Tinkers Creek is a 17 square mile watershed, which is a major tributary of Piscataway Creek. The two major tributaries of Tinkers Creek,


FIGURE 7

TINKERS CREEK &PISCATAWAY CREEK WATERSHEDS STRUCTURES IMPACTED BY 100 YEAR FLOODPLAIN



LEGEND:

(2) RESIDENTIAL STRUCTURES



Meetinghouse Branch and Pea Hill Branch, originate on Andrews AFB and flow in a southwesterly direction for above five miles to their confluence with the main Creek, which continues for about another five miles before meeting Piscataway Creek. Land use within the watershed is primarily residential with a considerable amount of undeveloped land remaining.

A total of 14 structures have been identified within the Tinkers Creek Watershed as being flood-prone during a 100 year storm. This total includes 4 residential structures and 9 commercial structures and 1 other structure. Figure 7 identifies the general location of these flood-prone properties.

The most severe flooding occurs along Coolridge Drive in the Coolridge Subdivision. For the 100 year flood, as many as eight existing structures will experience varying levels of flooding. There is an isolated home and two other structures located north of Southeast Trailer Park that are also flood-prone. In the western section of Southeast Trailer Park, across from Temple Hill Estates, approximately 30 trailer homes are within the 100 year flood limits. Because of the type of structures involved, the effect of flooding could be more severe than with conventional structures. On the northern end of the Rose Valley Airport runway, two commercial structures are within the floodplain limits. A number of roads and bridges within the watershed are also susceptible to flooding.

Tinkers Creek was the first basin to be studied by the Prince George's County Stormwater Management Technical Group. A Technical Data Base Report and Watershed Management Plan were completed in 1980 which addresses stormwater management and erosion control needs in the watershed. The recommended plan consists primarily of constructing three dry ponds within the Andrews AFB, one behind Georgia Avenue and a second at Branch Avenue both in Meetinghouse Branch and a third behind Branch Avenue and Paynes Branch. Together, the three detention ponds will remove all homes and commercial buildings within Tinkers Creek from the 100-year floodplain. They will also reduce the extent and frequency of flooding of roads and bridges. This project has been adopted by Prince George's County and included in the Capital Improvement Program. The project is expected to be completed by FY 1983.

3.27 Mattawoman Creek

Mattawoman Creek forms a major portion of the boundary between Prince George's and Charles Counties, with approximately 24 square miles of the watershed located in Prince George's County. Land use within the Prince George's County portion of the watershed is predominantly rural with scattered low-density residential, agricultural and forestry uses. Current plans, however, call for major residential, commercial and industrial development in the area adjacent to Route 301. Most of the existing development and subsequent flooding problems within the watershed occur in Charles County where several subdivisions encroach on the floodplain. Except for road flooding, the Prince George's County portion of the water-

shed seems to be free of flooding problems. No structures were identified by this survey. The Maryland Water Resources Administration is currently delineating the 100-year floodplain for this watershed. A Comprehensive Watershed Management Plan is not currently programmed for Prince George's County.

3.28 Lower Potomac

The Lower Potomac consists of a number of small watersheds directly tributary to the Potomac River in the southwest portion of Prince George's County below Piscataway Creek. This area is sparsely developed and flood-plains have not been delineated. No structures were identified by this survey as flood-prone in this area.

3.3 Patuxent River Sub-Watersheds

3.31 Upper Patuxent

The Upper Patuxent consists of the Patuxent River and its tributaries from the Rocky Gorge Reservoir to the confluence with Horsepen Branch. A considerable amount of development has occurred in the upper portion of this area which includes the City of Laurel. The area below the Baltimore-Washington Parkway is largely within the Patuxent Wildlife Research Center where floodplain disturbance is prohibited. Severe flooding has occurred in the City of Laurel on 5 occasions since 1933, including the most spectacular flooding in Prince George's County during tropical storm Agnes in June 1972. The most serious flooding occurs in a 4,600 foot long reach from just upstream of U.S. Route 1, south to Maryland Route 198. Numerous commercial properties including Laurel Race Track, Laurel Plaza Shopping Center, Laurel Pines Golf Course, WLMD radio broadcasting station and Montpelier Plaza Shopping Center are subject to flooding during the 100 year storm. A total of 79 structures have been identified within the Upper Patuxent area as subject to flooding including 30 residential structures and 49 commercial or other structures. Figure 8 identifies the general location of floodprone structures within the watershed.


Very little can be done to reduce flooding potential on the Upper Patuxent. The WSSC has adopted a policy of operating its water supply reservoirs above Laurel with flood control in mind as well as water supply and to carefully monitor upstream storm events in order to allow earlier and more gradual release of flood peaks. This should help to decrease the severity of flooding.

3.32 Horsepen Branch

The Horsepen Branch Watershed comprises approximately 6.5 square miles of land area in the vicinity of Bowie, Maryland. Land use within the basin is primarily residential. The Town of "Old Bowie" is centrally located within the watershed, with more recently developed residential subdivisions scattered throughout the area.


FIGURE 8

UPPER PATUXENT WATERSHED STRUCTURES IMPACTED BY 100 YEAR FLOODPLAIN



LEGEND:

2 RESIDENTIAL STRUCTURES



The 100 year floodplain of Horsepen Branch has not been delineated and the entire watershed has been identified as Zone "C" on the FIA map. For this reason and because very little development has occurred in the vicinity of the mainstem, no structures have been identified as flood-prone. Several tributaries to Horsepen Branch do cross under the Pennsylvania Railroad through inadequate culverts, which creates the potential for backwater flooding.

3.33 Western Branch Watershed

The Western Branch Watershed is the largest watershed wholly within the County, comprising 70 square miles of land area. Most of the watershed lies outside the Beltway; however, a portion is located inside the Beltway in the Forestville area. Land use in Forestville is a mixture of residential, commercial and industrial. Outside the Beltway, the basin is characterized by rural land uses, with residential development concentrated along Central Avenue and in the upper reaches of the watershed along Bald Hill and Folly Branches.


Most of the streams within the Western Branch Watershed have flat gradient and sluggish flows. The overbank areas are also flat and in many sections marshy. For these reasons, periodic flooding from stream overflow occurs along most of the mainstem and tributaries.

A total of 324 structures has been identified within the Western Branch Watershed as being flood-prone during a 100 year storm under full development. This total includes lll residential structures, 93 commercial and 120 other structures. Figure 9 identifies the general location of flood-prone structures within the watershed.

Several major sub-watersheds contribute flow to the mainstem of Western Branch. The most severe flooding occurs in the two uppermost subwatersheds along Folly and Bald Hill Branches. In these sub-watersheds a combination of floodplain encroachment, stream siltation and backwater effects from inadequate structure openings increase the incidences of flooding. Fifty (50) of the 111 flood-prone residential structures are located within these watersheds. There have been reports of frequent flooding of commercial and residential properties along Lanham-Severn Road, Wellington Place, 4th, 5th, and 6th Streets, adjacent to Bald Hill Branch. Another area of potential flooding is along Southwest Branch where roads are frequently closed by flood water, and some residential and commercial developments were built on flood-prone land. Fifty (50) structures including 20 residences are located within the Southwest Branch floodplain. The flooding is particularly severe at Hampton Mall near Central Avenue and Route 495. Figure 10 represents the distribution of flood-prone structures among the sub-watersheds of Western Branch.

Along the mainstem of Western Branch, flooding potential is most severe in the Town of Upper Marlboro where 89 structures have been identi-

PERCENTAGE OF FLOODPRONE STRUCTURES WESTERN BRANCH SUB-WATERSHEDS



fied as flood-prone. Several road crossings on the mainstem are closed for many hours each year due to overtopping.

Past efforts to control flooding within the watershed included construction in December 1964 of a local levee system along the mainstem near the Town of Upper Marlboro. A comprehensive Watershed Management Plan is currently being prepared for Western Branch. This Plan, when completed, will address stormwater management problems and erosion control needs and will recommend solutions to present and future flooding problems.

3.34 <u>Collington Branch Watershed</u>

The Collington Branch, a major contributary to Western Branch, has a long, narrow 23 square mile watershed which parallels the west side of Route 301 from Bowie to Upper Marlboro. Land use varies from single-family residential in the vicinity of Bowie to rural and agricultural uses throughout much of the remainder of the basin. A major industrial park is planned for a portion of the basin just south of Route 214. The watershed has remained mostly undeveloped and floodplain encroachments have been minimized. A total of 16 structures have been identified within the watershed as potentially flood-prone during a 100 year storm under full development. This total includes 11 residential structures 1 commercial and 4 other structures. In addition, 7 road crossings are wholly or partially within the floodplain; however, none of the major transportation arteries would be affected. Figure 9 identifies the general location of the flood-prone structures.

The most severe flooding within the waterhsed occurs near the confluence of Collington and Western Branches where 8 residential and commercial structures have been identified as flood-prone. Flooding of these structures would be due primarily to the backwater effect from high stages in Western Branch.

The U.S. Army Corps of Engineers completed a flood control project, consisting of floodwalls and channel improvements in 1964, near the Town of Upper Marlboro. There are no other flood protection measures within the watershed. A Comprehensive Watershed Management Plan is currently being prepared for Collington Branch. This Plan, when completed, will address stormwater management problems and erosion control needs. It will also recommend solutions to present and future flooding problems.

3.35 Charles Branch

Charles Branch is an 18 square mile watershed located east of Andrews AFB and south of Route 4. Charles Branch discharges into Western Branch near its confluence with the Patuxent River. Land use within the basin is primarily agricultural with a few scattered residential subdivisions. One large subdivision, Marlton has developed to the east of Route 301. The suburban development which has occurred in the watershed has been recent enough to be regulated so as to avoid floodplain encroachment. The 100

year floodplain has not been delineated and the watershed is identified as Zone "C" on the FIA maps. This survey did not reveal any structures within the watershed prone to flooding. A Comprehensive Watershed Management Plan for Charles Branch has not been prepared; however, one will be initiated in FY 83.

3.36 Middle Patuxent River

For the purpose of this survey, the Middle Patuxent is defined as the area along the Patuxent River from its confluence with Horsepen Branch to its confluence with Western Branch. The floodplain in this area is largely undisturbed except near Priest Bridge. This survey identified 6 residential structures within the 100 year floodplain. Figure 11 identifies the general location of these flood-prone areas.

Most of the flood-prone structures are located in the vicinity of Priest Bridge.

Very little can be done to control flooding in these areas except to prevent further encroachment in the floodplain and to minimize erosion to preserve existing channel capacity.

3.37 Lower Patuxent River

The Lower Patuxent Area is defined for the purpose of this study as the Patuxent River and its tributaries south of the Western Branch Watershed. This area is almost entirely rural with only scattered low-density development. The only exceptions are the Nottingham and Eagle Harbor communities and the Chalk Point Power Plant near the southeast tip of Prince George's County. Our survey did identify a total of 15 residential structures including 12 in Eagle Harbor as subject to potential flooding during a 100 year storm event. Figure 12 identifies the location of flood-prone structures in the Lower Patuxent Area.

FIGURE 11

MIDDLE PATUXENT WATERSHED

STRUCTURES IMPACTED BY 100YEAR FLOODPLAIN





FIGURE 12

LOWER PATUXENT WATERSHED

STRUCTURES IMPACTED BY 100 YEAR FLOODPLAIN



4.0 References

- 1. Booker Associates, Inc., "Beachcraft Court Stormwater Management Study, Prince George's County, Maryland", WSSC, November 1979.
- 2. Booker Associates, Inc., "Oxon Run Floodplain Study, Prince George's County, Maryland", WSSC, July 1979.
- 3. Clark, Finefrock and Sackett, "Indian Creek Stormwater Management Study, Prince George's County, Maryland", WSSC, December 1979.
- 4. Clark, Finefrock and Sackett, "Weldon Drive Stormwater Management Study, Prince George's County, Maryland", WSSC, August 1979.
- 5. Enviro Plan, Inc., "Environmental Assessment of the Henson Creek Relief Sewer and Stormwater Management Project", WSSC, January 1976.
- 6. Federal Insurance Administration, "Flood Hazard Boundary Maps",
 Department of Housing and Urban Development, August 1976.
- 7. Gannett, Fleming, Corddry and Carpenter, Inc., "Preliminary Stormwater Management Study at Allison Street-Brentwood on Northwewt Branch, Anacostia River", WSSC, April 1980.
- 8. Greenhorne & O'Mara, Inc., "Cattail Branch Floodplain Study, Prince George's County, Maryland", WSSC, June 1979.

- 9. Greenhorne & O'Mara, Inc., "Drum Avenue Drainage Study, Prince George's County, Maryland", WSSC, August 1979.
- Prince George's County Council's Task Force on Flooding, Report dated
 September 1974.
- 11. Prince George's County Stormwater Management Technical Group, "Tinkers Creek Comprehensive Watershed Management Plan", Prince George's County, October 1979.
- 12. Prince George's County Stormwater Management Task Force, "FY 1980 Comprehensive Stormwater Management Plan and FY 1980-1985 Capital Improvements Program".
- 13. U.S. Army Corps of Engineers, "Review Report on Flood Control and Allied Purposes, Patuxent River and Tributaries, Maryland, February 1975.
- 14. U.S. Army Corps of Engineers, "Henson Creek Floodplain Information Report", March 1966.
- 15. U.S. Army Corps of Engineers, "Floodplain Information, Piscataway Creek, Prince George's County, Maryland, November 1967.
- 16. U.S. Army Corps of Engineers, "Floodplain Information, Beaverdam Creek, Prince George's County, Maryland", September 1967.

17. Washington Suburban Sanitary Commission Adopted Six Year Capital Improvement Program, Fiscal Years 1982-1987.

APPENDIX "A" SAMPLE LETTER OF NOTIFICATION

APPENDIX A

Sample Flood Notification Letter

This letter of notification was sent to property owners whose homes were found by our analysis to be endangered by the 100 year floodplain. It served to notify the owners of their possible problem and the availability of Federally-subsidized insurance coverage.

Dear Property Owner:

In cooperation with the Maryland Water Resources Administration and the Coastal Zone Management Program, the Environmental Planning Division of the Prince George's County Planning Department has initiated an inventory of flooding problems within the County. Information is being gathered which will help the State assess the damage potential and cost of a major flood and plan for necessary relief measures.

Due to the scale of maps used and the nature of this survey, some of the properties identified may not actually be flood prone, but based upon a review of existing flood information, it appears that your property may be prone to flooding during a 100-year storm (a storm with a one percent chance of occurrence in any given year). I would like to emphasize that a conservative approach was taken in identifying flood-prone properties. Any specific information that you can provide based upon your personal observations of flooding in your area will greatly improve the accuracy of our data.

I would also like to take this opportunity to inform you of a Federally subsidized flood insurance program that is available to owners of flood-prone properties in Prince George's County. This program, which is administered by the Federal Emergency Management Agency, can provide you with protection from damage.

If you have any questions concerning the Flood Data Inventory Program or wish to provide us with information on flooding, or if you are interested in obtaining flood insurance, please contact the Environmental Planning Division at 952-3651 or 3652. We appreciate your cooperation and assistance.

Sincerely,

Dominic J. Motta

Environmental Planning Division

Daninic Q. Motta

DJM/nlb

APPENDIX "B" HIGHWATER ELEVATION OF SELECTED PRINCE GEORGE'S COUNTY BRIDGES

HIGHWATER ELEVATIONS SELECTED PRINCE GEORGE'S COUNTY BRIDGES

		Highwater E	
BRIDGE	STREAM	JUNE 21, 1972	SEPT. 22-26, 1975
Ammendale Rd.	Indian Creek	-	127.94
Bealle Hill Road	Mattawoman	106.03	104.12
Bock Road	Henson Creek	75.7 3	75.10
Brinkley Road	Henson Creek	110.76	113.79
Brock Bridge	Patuxent	-	116.70
Gallahan Road	Tinkers Creek	21.87	24.00
Livingston Road	Piscataway Creek	15.51	15.64
Metzerott Road	Paint Branch	-	74.05
Odell Road	Indian Creek	-	113.28
Old Baltimore Pike	Indian Creek	-	106.84
Old Ritchie Road	Southwest Branch	-	131.72
Oxon Hill Road	Henson Creek	-	15.93
Piscataway Road	Piscataway Creek	22.06	19.59
Ritchie Road	Ritchie Branch	· -	158.65
Sellman Rd.	Little Paint Branch	-	132.06
Rt. 202 and 408	Western Branch	21.86	24.40
Steed Road	Tinkers Creek	137.02	-
Sunnyside Avenue	Indian Creek	-	82.32
Surratts Road	Piscataway Creek	-	128.48
Temple Hill Road	Tinkers Creek	186.35	185.67
Temple Hill Road	Henson Creek	129.02	126.31
Tucker Road	Henson Creek	71.13	68.53
U. S. Rt. 1	Paint Branch	-	63.26
Water Street	Western Branch	17.90	22.08
White House Road	Southwest Branch	57.95	58.35

NOTE: The information contained in this appendix was supplied by the Prince George's County Department of Public Works and Transportation

APPENDIX "C" SELECTED COMMENTS ON FLOODPRONE PROPERTIES

SELECTED COMMENTS FLOODPRONE PROPERTIES

Anacostia River Watershed

Address	Comment
6603 23rd Avenue	Hurricane Agnes resulted in 6 ft. of basement flooding
6708 West Park Drive	Water reached window well during Agnes
6703 25th Avenue	Agnes caused 7 feet of basement flooding
4515 34th Street	Basement flooding Agnes - 8 feet David - 3 feet
4527 34th Street	Basement Flooding Agnes - 8 feet
4513 34th Street	Frequent basement flooding
6720 West Park Drive	Basement Flooding - Agnes
6609 24th Avenue	Basement Flooding - Agnes
6710 25th Avenue	Water surrounded house during Agnes
6604 24th Place	Basement Flooding l½ feet - Agnes
6415 24th Place	Frequent basement flooding
5012 Rittenhouse Street	Basement Flooding - Agnes
5004 Rittenhouse Street	Basement Flooding - Agnes
5003 Ravenswood Place	Water reached front steps during Agnes
8818 Patricia Court	Frequent flooding until levee built
4223 Metzerott Road	Frequent flooding until levee built

SELECTED COMMENTS FLOODPRONE PROPERTIES Beaverdam Creek

Address

Comment

5203 N. Englewood Drive

Water has come close to house

Henson Creek

5410 Stratford Lane Frequent flooding until drainage

improvements were made

2111 Calhoun Street Worst flooding has reached patio

4304 Weldon Drive

No flooding has occurred since

the Temple Hill Road culvert was

enlarged

5920 Ladd Road Frequent backyard flooding;

occasional basement flooding

up to 2 feet.

6413 Roberts Drive Frequent property flooding;

no basement flooding

Piscataway Creek

7802 Knollwood Basement flooding on 3 occasions -

Agnes, Eloise, Winter 1979

11753 Crestwood Drive Basement flooding - Agnes, David;

maximum 2 feet in basement

4020 Floral Park Road Severe and frequent flooding

Tinkers Creek

7003 Coolridge Drive

Basement flooding

SELECTED COMMENTS FLOODPRONE PROPERTIES

Western Branch

9103 Sheridan Court	Frequent yard and basement flooding
9214 6th Street	Frequent basement flooding
9219 3rd Street	Severe flooding; 6 ft. in basement 8/31/81
9111 Wellington Place	Flood of 8/31/81 came to house
8811 Magnolia Drive	Flooded 3 times in 10 years; 4 feet in basement 8/31/81
11304 Sherington Court	House has not flooded; water has come close

APPENDIX "D" INVENTORY OF FLOODPRONE STRUCTURES

STRUCTURE*

ELEVATION

1st Floor 100-year (FT M.S.L.) (FT M.S.L.

ADDRESS TYPE

ANACOSTIA RIVER

NORTHWEST BRANCH

Residential	3400 Allison Street, Brentwood, MD 20722	27
" "	3404 " "	"
'' 'I	3406	;; It
" "	. 3406	
" 11	3410	
	3412	
) II	3401	11
 II	3403	"
" "	3405	"
'' 11	5407	
"	3409	"
" II	3413	
 H	3413	"
11	5417	"
11	3300 -	
, " ()	3304	
n	3300	H ·
11	3308	
'' U	3301	11
	3503 " "	0
. "	3505 " "	
II 	3507 "	11
	3600 " "	11
II 	3602 "	
	3604 " "	11
	3606 " "	11
li .	3603 " "	Ш
Residential	2518 Amherst Road, Adelphia, MD 20783	65
Residential	3201 Arundel Road, Mt. Rainier, MD 20822	28
Residential	2521 Avalon Place, Adelphi, MD 20782	51
	Louis March Maddy Mad Philip 115 Louis L	
Residential	3316 Buchanan St., Mt. Rainier, MD 20822	31
U	3318-3328 Buchanan St., Mt. Rainier, MD 20822	11
• II	3314-3324 Buchanan St., Mt. Rainier, MD 20822	II
	3331-3337 Buchanan St., Mt. Rainier, MD 20822	11
Residential	3300-3304 Chauncey Pl., Mt. Rainier, MD 20822	32
n	3306-3310 " "	11
	3259-3263 "	11
	3312-3316 " "	11
	3318-3320 " "	11
	3322-3328 " "	11
	3330-3338 " "	11
	D 7	

STRUCTURE

ELEVATION 1st Floor 100-yea <u>S.I.</u>

TYPE	ADDRESS (FT M.S.L.)	(FT M.S
Residential " " " " " "	3200-3214 Chillum Rd., Mt. Rainier, MD 20822 3204-3216 " " 3218-3234 " " 3350-3352 " " 3366-3370 " " 3360-3364 " "	32
Residential "" "" "" "" "" "" "" "" "" "" "" "" "	2701 Nicholson St., Hyattsville, MD 20782 2703 " " 2705 " " 2707 " " 2709 " " 2711 " " 2713 " " 2715 " " 2717 " " 2719 " " 2721 " " 2723 " " 2724 " " 2725 " " 2727 " " 2729 " " 2731 " " 2733 " "	32 0 0 0 0 0 0 0
Residential " " " " " " " "	3157-3163 Queens Chapel Rd., Mt. Rainier, MD 20822 3117-3121 " " 3123-3127 " " 3129-3135 " " 3145-3149 " " 3137-3143 " " 3220 " " 3290 " "	32
Residential " "	3300-3310 Queenstown Dr., Mt. Rainier, MD 20822 3301-3311 " " 3304-3312 " "	32 "
Residential	8211 Riggs Rd., Adelphi, MD 20783 8401 " " 8402 " "	75 "

STRUC	ELEVATION 1st Floor 100-year	
ТҮРЕ	ADDRESS	lst Floor 100-year (FT M.S.L.) (FT M.S.L
Residential	2300 Rittenhouse St., Chillum, MD 20782	49
u	2302 " " "	n n
**	2304	H .
	2300	11
ii N	2300	11
81	2310	11
	2312	
41	2314	u u
	2310	ii
11	2318	18
31	2320	et.
	2322	
ii	2301	::
	2303	
11	2305	
" "	2307	
	2309	11
•	2311	
e it . n	2313	. "
"	2315 " "	
Residential	2301 Sheridan St., Chillum, MD 20782	51
Residential	2301 Sheridan Sc., Chiridii, No. 20702	, 31
ti .	2303 " "	11
· 11	2505	ts
	2307 -	· · ·
11 ·	2309	
11	2311	 Y
11	2313	11
48	2313	
11	2401	tr.
Residential	2403 " " " 2405 Sheridan St., Chillum, MD. 20782	F1
Residential	2405 Sheriuan St., Chillum, Mb. 20762	51
	2507 " " " " " " " " " " " " " " " " " " "	te to the state of
15	2511 " "	. "
	2513 ". "	
11	2515 " "	19
	2517 " "	
11	2517	
н	2521 " "	, !!
н	2523 " "	
u	2300 " "	
11	2302 " "	
. 1	2306 " "	
n .	2308 " "	10
	2402 " "	*U
II .	2404 " "	
88	2404	88 ·
16	2410 " "	11
	4410	T.

<u>s t r u</u>	<u>C T U R E</u>	ELEVATION
TYPE	ADDRESS	lst Floor 100-ye (FT M.S.L.) (FT M.S.
Residential	2513 Van Buren St., Chillum, MD 20782	51
11	2515	"
ti .	2517	11
și .	2519 " "	11
H	2516	N
u ·	2518 " "	11
. 11	2520 " "	It
Residential	3404 Webster St., Brentwood, MD 20722	28
11	3408	11
at .	3410 " "	H
11	3412	u
11	3401 " "	н
II.	3403 " "	n
· 11	3407 " "	11
ır	3409 " "	11
11		
•	3413 " "	,
Residential	6700 West Park Dr., Chillum, MD 20782	65
11	6702 - "	11
II	6704 " "	ii ii
n .	6706	44
11	6708 "	ti .
18	6710 "	n
19	6712 . "	· · · · · · · · · · · · · · · · · · ·
. ti	6714	ti
H	6716	11
u	6718 " " .	
16	6720 " "	
Residential	6802 West Park Dr., Chillum, MD 20782	65
NESTOCITO I AT	6804	
		•
Residential	7706 West Park Dr., Adelphi, MD 20783	65 "
lt.	7708 " "	
11	7710 " "	ji
18	7703 " . "	
16	7705 " "	11
u	7707 " "	11
11	7711	11

STR	<u>UCTURE</u>	ELEVATION
TYPE	ADDRESS	lst Floor 100-year (FT M.S.L.) (FT M.S.L.
•	· · · · · · · · · · · · · · · · · · ·	
Residential		722 27
u 	3402	
11	3404	* 8
	3406 " "	• •
11	3408 " "	11
ll .	3410 " "	· "
11	3403 " "	II
	3405 " "	:1
11 12	3407 "	ii .
II .	3409 "	
17	3411 " "	9?
11	3413 " "	£6
u	3415 " "	es
11	3500 " "	. n
Residential	2513 Woodberry St., Adelphi, MD 2	0783 65
Posidontial	' 6603 23rd Ave., Chillum, MD 20782	51
Residential		
II.	6605 " "	18
II .	6607 " "	H
	6609 " "	. "
Residential	6602 23rd Place, Chillum, MD 2078	51
п	6604 " "	(t
u ·	6606 " "	18
ii	6608 "	11
35	. 6601 " "	
u	6603.	н
	6605 " "	li .
u .	6607 " "	11
u	6609 " "	
		· n
	6611 " "	·
Residential	6602 24th Ave., Chillum, MD 20782	53
11	6604 " "	11
t i	6606 "	48
Residential	6608 24th Ave., Chillum, MD 20782	53
II .	6610 " "	. "
10	6612 " "	• 11
19 ,	6603 " "	• ·
	6605 " "	· II
. "	6607 " "	11
. 11	6609 " "	
16	6611 " "	
H ,	6613 "	
11	6615 " "	
10	6617 " "	tf
	6617 " "	. 68

STRU	CTURE	<u>ELEVATION</u>
TYPE	ADDRESS	lst Floor 100-year (FT M.S.L.) (FT M.S.L
Residential	6602 24th Place, Chillum, MD 2078	
Residential	6604 " "	. "
11	6606 " "	n .
	6608 " "	· · · · · · · · · · · · · · · · · · ·
10	6610 " "	· · · · · · · · · · · · · · · · · · ·
10	6612 " "	, n
11	6614 " "	H
II .	6616 " "	ti .
ii .	6618 " "	, a
II .	6620 " "	11
ii .	6603 "	H
11	6605 " "	tt
H	6607 " "	II
II	6609 "	·
n ·	6611 " "	Ħ
11	6613 " "	n
	6615 " "	l)
n	6617 " "	<u>.</u>
11	6619 " "	· · · · · · · · · · · · · · · · · · ·
n	6621 " "	ц
H°	6623 " "	
и .	6625 "	. н
.	•	
Residential	6700 25th Avenue, Chillum, MD 207	
	6/02	· ·
: i	6704 " " " " " " " " " " " " " " " " " " "	• 11
	. 6700	•
	6708 " "	lt .
u	6710 " "	
H .	6701 " "	11
81	6703 " "	!!
II .	6705 " "	"
. II	6707 " "	***************************************
11	6709 " " " "	
tt.	6711 " "	N
11	6713 " "	ti .
11	6715 " "	ıı
	4704 21 th D1 Mt D 1 th 220 25	
Residential	4704 31st Pl., Mt. Rainier, MD 20	0822 28

S T R U C	TURE	ADDRESS		ELEVATION 1st Floor 100-ye (FT M.S.L.) (FT M.S.
	•			-
Residential	4519	32nd St., 1	Mt. Rainier, MD 20822 -	28
п	4521 4522			II
H	4523 4525	II H	· "	· • • • • • • • • • • • • • • • • • • •
II 	4525 4527	II	II	n
	4529	n ,	11	. п
II 	4529 4531	11	u	п
11 11	4518	II	н	и.
, , , , , , , , , , , , , , , , , , ,	4520	II	11	н
11	4522	11	ii .	и.
 H	4524	11	II	11
n ·	4526		11	. H
	4528		- 11	ti
	4530	11	II .	II
"				
Residential	4501 3		Brentwood, MD 20722	28
и И	4503	11	บ	11
11	4505	11	11	li .
'' 	4507	Ħ	11	11
" !!	4509	II .	11	п
· H	4511	18	н ,	· u
	4513	"		П
 H	4515	II 		n
II	4523	11	II 	, II
н	4527	"		II.
lt .	4529 4520	11	11	II
ш	4528 4520	 11	n	II .
u	4530 4532	11	· 11	11
II .	4532	11	Tr	п
H	4601	11	u .	11
ti	4603		" "	
	4605	•	"	II
Residential	4600 3	7th St., B	rentwood, MD 20722	27
Commercial	5390 A	ger Rd H	yattsville, MD 20782	32
	5620	- 0	II	32
	5950	П	Iŧ	н
II II	6000	11	11	n .
11	6002	H	и	u

STRUC	T U R E		ELEVATION
TVDF	ADDDECC		lst Floor 100-ye (FT M.S.L.) (FT M.S
ТҮРЕ	ADDRESS	<u> </u>	(FT M.S.L.) (FT M.S
Commercial	2486-2490 Chi	11um Rd., Chillum, MD 2078	32 32
11	2426	11 11	11
11	2430	u n	11
н	2440	11 11	. 11
11	2460	11 11	ıı
	2464	II II	ll .
	2490	u u	
si .	2400	n n	11
	2310-2314	11 11	, н
11	2222	н н	и
II.	2309	D II	11
II	2130	II II	Ц
Commercial	1901 Hamilton	St., Hyattsville, MD 2082	22 32
	2001 "	II	. 11
	2781 "	11	11
II	2801 "	и	11
Common de 1	2171 2101 0	and Change D.J. Mr. D.J. to	. MD 00000 20
Commercial	3171-3191 Que	ens Chapel Rd., Mt. Rainie	er, MD 20822 32
			•
Commercial	2500-2520 Uni	versity Blvd., Adelphi, MD	20783 65
. 0	2400-2426	. "	te
	2501	•	tı
н .	2503	H H	H
	2505		łı
	2507		H
	2509	•	tt
	2511	н	и

	STRUCTURE	ELEVATION
		1st Floor 100 year
TYPE	ADDRESS	(FT M.S.L.) (FT M.S.L
	SLIGO CREEK	
	SLIGO CREEK	
Residential	2001 Oglethorpe St., Chillum, MD	20782 46
II II	2003	10
11	2000 " "	п
II .	2002 " "	11
Residential	1903 Oliver St., Chillum, MD 207	
	1905	II
II 	1907 " "	
11	1909 " "	ti
11	1911 " "	·
11	1913 " "	11
п	1915 " "	ß
H	2003 " "	II
11	2005 " "	II.
II.	2007 " "	H .
н	2009 "	н
11	2009	11
11	2002	 H
	2004	
	2006 " "	II .
II	2008 " "	П
Residential	2001 Peabody St., Chillum, MD 20	782 46
"	2003 " "	702 40 II
н	2005 " "	II
11		 H
11	2007	
:- !I	2000	II
	2002 "	(I
II	2004 " "	11
II	2006 "	II
11	2008 "	· II
Residential	2002 Dowbattan Bd Chillum MD	20782 46
Residencial	2003 Powhattan Rd., Chillum, MD	20782 46
н	2005	" II
II	2007	
 II	2000 .	!!
	2002 "	II
II 	2004 " "	n .
II	1901 " "	11
II	1903 "	n .
ii .	1905 " "	11
11	1907 " "	n .
II	1909 " "	II
II.	1902 "	п
II	1904 " "	п
Residential "	2001 Rittenhouse St., Chillum, MD 2003	20782 52

·	STRII	CTURE	<u>ELE'</u>	ELEVATIO		
TVDC	<u> </u>		1st Floor	100 <u>)</u> (FT N		
TYPE		ADDRESS		(FT M.S.L.	<u> </u>	
			•		-	
Residential	2005 Ritte	nhouse St., C	Chillum, MD 20782		52	
11 H	2007		11	•	н	
11	2009		II -	• '	н	
и -	2011	11 11	II 			
	2000	11	11 11		11	
11	2002 2006	ii	 11		11 11	
· ·	2010	n	 II		11	
O .	2012	II	н		n "	
Residential	2007 Roano	ke St., Chill	um, MD 20782		E 2	
nesidential	2009	" (IIII	וטווי, ווט בטיסב	·	52	
· n	2011	, II	u		· · ·	
H	2013	11	11	•	Ħ	
и .	2000	. 11	11		H	
H	2002	II	11		11	
II	2004	11	11		и.	
II	2006	Ĥ	t1	•	11	
II 	2008	H	11		Ħ	
H	2010	11	11		11	
11 11	2012	# 	II 		н .	
" . ()	2014	ł1 11	11 11			
. "	1900 1902		u u		11 11	
Residential		Dankway Chi	11 MD 20702		4.0	
vezidenciai	6023	Parkway, Chi	11um, MD 20782		46	
O C	6025	н	11		11	
	6027	11	11		11	
II	6029	' н	II		11	
II .	6103	n	II		11	
11	6105	н	. 11	•	11	
II .	6107	11	11		11	
II	6201	11	n .		11	
II	6203	н	II		11	
II 	6205	11	II .		11	
n n	6207	11	!!	•	11	
" "	6209	11 H	13 11	•		
ii .	6211	• " .	u u		H H	
B .	6213.		10			
Н	6215 6217		. " II		"	
ú '.	6219		n n			
. 0	6221	n	11		11	
u ·	6223	11	II.		н	
н	6225	II	u ,		H	
n ·	6227	H .	u .		п	
II	6229	n .	n		н	
	· — — -					

						ELEVA	TIO
	STRU	CTURE		~	lst	Floor	100 y
TYPE		ADDRESS			(FT	M.S.L.)	(FT M
, , ,		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			<u> </u>		
			:			•	
Residential	6221 5144	Parkway, Ch	villum MD	20782			46
NEST LUEITO HAT	6233	J Faikway, Gi	ייוו און אווי ווו	20/02			40
II .	6303	и .	11 -			•	52
u .	6305	11	н	•			3 <u>Z</u>
n ·	6307	11	11				11
H .	6309	. 11	11				u
H .	6311	n ·	11				11
II .		n	11				11
n	6313	11	11 1				11
II .	6315	II	11				II.
11	6317	11	11				н
11	6319	 H	II.				
11	6321	H	11				Ħ
II	6323	 H					11
, , , , , , , , , , , , , , , , , ,	6403	 II					
11	6405				3		
0	6407	11					11
u u	6409			•		,	
" "	6411			•			••
" II	6413	"	**				11
H	6415	 H	"				
. "	6417	**	"				- 11
и	6501	11	" "				59
" "	6503		" H				#1
" "	6505	"	•				
	6507		"				11
11 11	6509	11 15	11				"
"	6511	.,				•	11
Dooddontioi	2000	C4 Ch	: 11 MD	20702			50
Residential		rset St., Chi	טוא, ווווווווווווווווווווווווווווווווווו	20782			52
	2002						
 */	2004		tí				
	2006						
11	2001		 11	-	•	•	
 H	2003		" "				11
 	2005		 H				. 11
,,	2007	"	••				H
Residential	2000 Tuels	Alaman Ct. Cl	.:11 MD	20702			
RESTUBILLAT		erman St., Ch	טויין וווווון, ויוו	20782	•		59
II	. 2002		." H	•			 11
11	2004	11					
n .	2006	"	. "				
u ,	2001		. "				11
"	2003	"	11				11
 II	2005		" "				
	2007	••	. "				н
Residential	6020 20+h	Ave., Chillu	um, MD 207	792			A.C
Hestacherat	6022	Ave., Citill	וווא בייווג בייווג וו	, or			46
II	6024	ii .	11				
	0027						

	CTDUCTUO		ELEVATION		
	STRUCTUR			lst Floor	100 year (FT M.S.
TYPE	ADDI	RESS		(FT M.S.L.)	(FT M.S.
		;			
Residential "	6102 20th Ave., Cl	nillum, MD 20782	•		46
	6104 "	II .	-	•	11
. 11	6106 "	II 			II .
H H	6200 "	II 			II
11	6202 "	II 			II
11	6204 "	11-			11
11	6206 "	11			11
'' II	6212 "				11
 II	0214				11
 II	0210				11 -
 11	.0210	11			11
" II	0220	H .			
	0222	11			н .
	, 0224	II 			. "
n n	6226 ."	11			13
11	6228 "	II		•	н
" "	0230	H			Ħ .
и	6302 "			•	н
	6304 "	II.			П
	6306 "	11			11
"	6308 "	11			H .
II 	6310 "	II			H
	6312 "	H			t i
11 11	6021 "	, II			H
	6023 "	II .			lt .
II	6025 "	н			11
H 1	6027 "	11			H
H 	6103 "	II			II
II 	6201 "	11			11
II 	6203	Н			· п
, II	6207 "	II	•		11
II 	6209 "	H .			11
II	6211 "				n
11	6213 "	11			11
II .	6213 " 6215 "	11		•	11
u .	6217 "	II			П
"	6219 "	II			u
	6221 "	ъ. н			11
ii .	6223 "	и .			II
II .	6225 "	и .			, U,
· ·	6227 "	H -			
H	6314 "	î II			52
u ,	6316 "	H .		•	B
ii .	6318 "	11		•	н
II .	6320 "	II			11
11	6320 " 6322 "	m:			tt '
ш	6402 "	, II			ti .
н	6404 "	11			II .

TYPE ADDRESS (FT M.S.L.) Residential 6406 20th Ave., Chillum, MD 20782 " 6408 " " " 6410 " " " 6410 " " " 6414 " " " 6500 " " " 6504 " " " 6504 " " " 6504 " " " 6508 " " " 6508 " " " 6508 " " " 6510 " " " 6704 " " " 6704 " " " 6704 " " " 6705 " " " 6706 " " " 6706 " " " 6707 " " 6708 " " 6708 " " 6708 " " 6708 " " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " 6708 " " " 6708 " "	T I O N 100 yea
Residential 6200 20th Place, Chillum, MD 20782 Residential 6200 0	(FT M.S
Residential 6200 20th Place, Chillum, MD 20782 Residential 6200 0	
Residential 6200 20th Place, Chillum, MD 20782 Residential 6200 0	52
## 6410 ## 6414 ## 6500 ## 6502 ## 6504 ## 6508 ## 6508 ## 6508 ## 6508 ## 6202 ## 6202 ## 6204 ## 6208 ## 6208 ## 6210 ## 6212 ## 6212 ## 6214 ## 6216 ## 6218 ## 6224 ## 6224 ## 6224 ## 6224 ## 6224 ## 6226 ## 6228 ## 6226 ## 6228 ## 6220 ## 6228 ## 6220 ## 6228 ## 6220 ## 6228 ## 6220 ## 6228 ## 6220 ## 6228 ## 6220 ## 6228 ## 6220 ## 6228 ## 6220 ## 6228 ## 6220 ## 6228 ## 6220 ## 6228 ## 6220 ## 6228 ## 6220 ## 6228 ## 6220 ## 622	11
## 6412 ## ## ## ## ## ## ## ## ## ## ## ## ##	11
## 6500 ## ## 6502 ## ## 6504 ## ## 6506 ## ## 6508 ## ## 6500 ## ## ## 6500 ## ## 6500 ## ## ## 6500 ## ## ## 6500 ## ## ## 6500 ## ## ## 6500 ## ## ## 6500 ## ## ## 6500 ## ## ## 6500 ## ## ## 6500 ## ## ## 6500 ## ## ## 6500 ## ## ## 6500 ## ## ## ## 6500 ## ## ## ## ## ## ## ## ## ## ## ## #	II
	11
	59
Residential 6200 20th Place, Chillum, MD 20782 6508	11
Residential 6200 20th Place, Chillum, MD 20782 6202	n
Residential 6200 20th Place, Chillum, MD 20782 6202	11
Residential 6200 20th Place, Chillum, MD 20782 " 6202 " " " 6204 " " " 6206 " " " 6208 " " " 6210 " " " 6212 " " " 6214 " " " 6216 " " " 6218 " " " 6220 " " " 6220 " " " 6220 " " " 6224 " " " 6226 " " " 6228 " " " 6228 " " " 6203 " " " 6203 " " " 6203 " " " 6205 " " " 6207 " " " 6209 " "	II
	11
6204 " " " " " " " " " " " " " " " " " " "	46
	11
6208 " " " " " " " " " " " " " " " " " " "	П
	li .
	ti .
	11
	П
6216	11
6218	н
6220	n .
" 6224 " " " " " " " " " " " " " " " " " "	н
" 6226 " " " " " " " " " " " " " " " " "	H
" 6228 " " " " " " " " " " " " " " " " " "	u
" 6201 " " " " " " " " " " " " " " " " " " "	
" 6203 " " " " " " " " " " " " " " " " " " "	11
" 6205 " " " " " " " " " " " " " " " " " " "	"
" 6207 " " " 6209 " " " 6307 " " "	
6207 " 6209 " " " 6307 " "	11
6307 " "	11
030/	11
6315 " "	59
	Н
0403	II .
6409	11
" 65 <u>0</u> 3 " "	H.
" 6505 " "	II .
" 6507 " "	11

STRUCT	URE			ELEVA	TION
ТҮРЕ	ADDI	RESS		lst Floor (FT M.S.L.)	100-year (FT M.S.L.
Danida uktop	0000 01	orthon Ch. Chill	MD 00700	•	50
-Residential		ridan St., Chilly	m, MD 20/82		52
. 11	2002	- II II			11
H	2004 2006	n n			11
и .	2001	II II			n
u	2003	ii ii			н
a	2005	11 11			n
н	2007	II II		·	н
Residential		enswood St., Chil	1um, MD 20782		52
, II II	2002	- 41 · · · · · · · · · · · · · · · · · ·			. 11
n	2004	" " II II			1)
	2006	" "			11
	2001	., ., ., .,			 u
 . n	2003		,		" "
	2005	"			••

\	STRUCTURE	ELEVATION
TYPE	ADDRESS	lst Floor 100 year (FT M.S.L.) (FT M.S.L
	NORTH EAST BRANCH	
Residential	4908 East-West Hwy., Riverdale, MD 20840	29
Residential	5309 Greenway Dr., Edmonston, MD 20781 5311 " "	21
Residential .	5311 Patterson Rd., Riverdale, MD 20840	29
	5313 " " 5315 " "	n
н	5317 " "	11
11	5312 " "	II.
II	5314 " "	п
11	5316 " "	H
П	5318 " "	II
11	5320 " "	u
Residential	5301 Powhatan St., Riverdale, MD 20840	29
" II	5303 " "	H H
 11	5305	и
11	5307 " " 5311 " "	п
II .	5313 " "	н
Residential	5414 Quesada Rd., Riverdale, MD 20840 5422 " "	29
Residential	5301 Quintana St., Riverdale, MD 20840	29
II	5303 " "	п
II	5305 " "	н
II	5302 " "	н
Residential	4909 Ravenswood Rd., Riverdale, MD 20840	29
II	4911 " " 4913 " "	n n
II	5003 " "	 II
n	5005 " "	II
II.	5007	п
	5009 " "	11
11	5011 " "	O O
H	5004 " "	. 11
II	5006 " "	п
II 	5008 " "	н
1) 1)	5010 " " 5012 " "	
Residential		20
וו	5000 Rittenhouse St., Riverdale, MD 20840 5002 "	29
II.	5004 " "	п
H	5006 " "	11

		ELEVATIO		
	<u>STRUCTURE</u>	1st Floor	100 y	
TYPE	ADDRESS	(FT M.S.L.)	(FT M	
	;			
Residential	5008 Rittenhouse St., Riverdale, MD 20840		29	
II	5012 " "		П	
Residential	5306 Riverdale Rd., Riverdale, MD 20840	•	25	
H · · · · · · · · · · · · · · · · · · ·	5308 . " "		## ##	
	5312 " " 5314 " "		. "	
II .	5316 " "		11	
н	5318 " "		11	
II .	5320 "		11	
11	5322 "		11	
H ,	5324 " "		II.	
Residential	5006 Sheridan St., Riverdale, MD 20840	·	3 1	
	5008 " " " " " " " " " " " " " " " " " "		n	
11	5012 " "		Ħ	
111	5005 " "			
H	5007 " "		H	
u ´	5009 " "		11	
n ·	5011 " " .		11	
II	5013 "		U	
Residential	5005 Somerset Rd., Riverdale, MD 20840		31	
11	5007 " "		u .	
H	5009 " "		H	
Residential	6303 Taylor Rd., Riverdale, MD 20840		29	
ıı ·	6305 " "		11	
II.	6311 " "		. #	
	6313 "		ti.	
11	6315 " "		11	
II.	6317 " "	•	ti	
Residential	5007 Tuckerman St., Riverdale, MD 20840		33	
tt	5011 " " "	•	11	
	5013 "		41	
II .	5015 "	•	11	
11	5017 " "		П	
	5012		11	
!!	5014 "		#1	
	5016 " "	•		
11	5018 " " .			
II .	3020		11	
Residential "	6120 54th Ave., Riverdale, MD 20840		25	
n n	0122		"	
" 11	0124			
11	6126 " " 6200 " "		П	
!!	6202 " "		Ħ	
II .	6204 "	•	**	
	·			

STRUCTURE					ELEVATION			
TYPE	ADI	DRESS			Floor M.S.L.)	100 year (FT M.5.L.		
Commercial	6250-6270 6300	Kenilworth Ave.,	Riverdale, ME	20737		31		
n n	6322-6324 6328	# #	11 11			11 11		
H H	6408 6410	. 11 H	n n			11 11		
. H	6504 6510	11	ti 11			33		
n n	6600 6715	. "	11 11			11		
II	6801	II .	11			68		

	STRU	CTURE		ELEVA	T I 0 N
ТҮРЕ		ADDRESS		lst Floor (FT M.S.L.)	100 yea (FT M.S.
	•	INDIAN	CDEEL		
		INDIAN	CREEK		
Residential	5101 Cleve	land Ave., Co	llege Park, MD 20740		52
H	5402	11	II .		11
n .	5500	и	"		ŧi
44	5502	II	11		II
II	5519	11	11 1	•	11
Residential	4906 Navah	oe St., Colle	ge Park, MD 20740		60
n	4910	Ü	ŭ		11
H	5009	u	li .		58
n .	5011	II	11		11
n	5013	11	и		I)
11	5101	H	II		н
н	5103	. "	II .		n
n	5105	181	II .		u
П	5107	ŧŧ	п		11
II	5109	II	n .		11
н	5004	II .	li .		11
u	5010	II .	ti .		Ħ
u	5014	II	11		11
u	5100	11	u		11
11	5106	11	и		H
II .	5108	II .	и .		11
ч	5110	11	н		II
11	5112	H	u		II .
H	5114	11	11 11		11
11	5116	11	11		#1
	5118		11		H
II	5120	II 	ii .		#
11	5122	11	, u		n
11	5124	n	• 11		11
II	5126	11	u		11
Residential	2000 Raven	swood St., Ch	illum, MD 20782		52
11	2002	Ð	H		H
II .	2004	II .	1 i		n
II	2006	13	ti		n
II	2001	0.	u		n
11	2003	II	u		11
и	2005	11	u .		n n
Residential	5500 Richm	ond Ave., Col	lege Park, MD 20740		50
Residential	2000 Sheri	dan St., Chil	1um, MD 20782		52
II .	2002	11	ti		H
11	2004	H	ii		41

STRUCTURE

	E L C V	A T T O N
	STRUCTURE 1st Floor	A T I O N 100 year
TYPE	ADDRESS (FT M.S.L.)	(FT M.S.
	: .	70000
Residential	2006 Sheridan St., Chillum, MD. 20782	52
11 10	2001 " "	. 11
11	2003 " " 2005 " "	11
11	2007 " "	li
Residential	8000 51st Ave., College Park, MD 20740	65
	8002 " " "	ti 11
II ,	8000	n
ii	8001	11
it	8003 " " 8012 " "	\$C
11	8108 " "	11
п .	8105 " "	¢t
n .	8111 " "	#
t)	8113 "	84
11	8115 " "	Ħ.
II	8117 "	. 88
Residential	8002 54th Ave., College Park, MD 20740	64
11 N	8004 " "	18 18
11	8000	ii
-	8008 " "	
Commercial	5502 Albany Ave., College Park, MD 20740	52
11	5504 "	61
n	5507 " "	89
Commercial	5503 Atlanta Ave., College Park, MD 20740	52
	5505 " "	.
Commercial	5107 Berwyn Rd., College Park, MD 20740	54
11	5111 " "	86
11	5113 " "	£8 -
11 31	5119 " .	£1
11	5113 " " 5115 " "	**
, n	5115	;; ;;;
	5117 "	•
Commercial	4905 Navahoe St., College Park, MD 20740 5134 "	60 58
Commercial	8100 Rhode Island Ave., College Park, MD 20740	58
Commercial	8005 51st Ave., College Park, MD 20740	65
Commercial	8300 54th Ave., College Park, MD 20740	65

STRUC	TURE		ELEVATION
ТҮРЕ	ADDI	RESS	lst Floor 100-yea (FT M.S.L.) (FT M.S.L
; 1 f la	7,50.		
	PAINT	BRANCH	
Residential	9002 Boteler L	ane, College Park, MD 20740	78
II .	3000		11
II II	9007 "	II 11	. II
"	9041 "	u	
Residential	4800 Lakeland	Rd., College Park, MD 20740	58
II 	4002		
11 11	4808 " 4812 "	"	. II
 11	4012	 II	 . II
	4300	 H	
п	4902 " 5002 · "	ii	
11	5004 "		60
. 11	5008 "	II .	II.
11	5013 "	п	11
II	5014 "	n .	0
н	5015 "	H	11
H	5016 "	II	ll .
II	5019 "	. "	
II	5021 "	II	, t 1
9	5022 "	n .	tı
H	5100 "	n	64
II	5102 "	ıı	II
II 	5103 "	II	"
11 11	5104 "		H
!! !!	5108 "	"	. 11
и	3103		
II	5110 " 5111 "	и .	ii
			~-·
Residential	4101 Metzerott	Rd., College Park, MD 20740	75
 II	4103	 H	п .
u	4105 " 4109 "		
II .	4201 "	· • • • • • • • • • • • • • • • • • • •	11
II .	4203 "	n ·	II
H	4221 "	u ,	n
- -	4223 "	11	н
Residential	8802 Patricia (Court, College Park, MD 2074	75
II II	8804 "	"	II.
11	8806 "	п	и
11	8808 "	н	11
II	8810 "	# 	II
II	8812 "	. II	н
	•		

STRUCTURE

<u> </u>	L	<u> </u>	V	A	1	1	0	N	
ļst									ear
(FT	Μ.	S.		.)	- 1	(F !	- ħ	1 S	

TYPE ADDRE	~~
: YE'F ALLIER F	``
TITE	J J

	PAINT BRANCH	
	TAINT BRANCIT	
Residential	8814 Patricia Court, College Park, MD 20740	75
" "	8816 " " "	() {)
n	8818 " " " 8803 " " " " " " " " " " " " " " " " " " "	
	8805 " "	
H	8807 "	11
· · · · · · · · · · · · · · · · · · ·	_8809 "	11
п	8811 "	!!
п	8813 "	11
11	8815 "	!!
II 	8817 "	11
II.	8819 " "	11
Dogidantial	0000 Tanada Lana Callana Paul ND 00740	mo pu
Residential	8000 Travis Lane, College Park, MD 20740	75
II .	8002 " " " " " " " " " " " " " " " " " "	 II
II .	8001 " "	
n	8003 " "	II
и	8005 . "	11
II	8007 " "	II.
Commercial	4902 Calvert Rd., Riverdale, MD 20737	46
	4917-4923 Calvert Rd., Riverdale, MD 20737	
Commercial	4911-4917 College Ave., College Park, MD 20740	46
n .	5001	11
11	5003 "	Ħ
11	5005 "	fs
н	5012 "	Ħ
Commercial	1303 Cpl. Frank Scotts Dr., College Park, MD 20740	F0
"	6707 " " " 20740	52 "
Commercial	4915 Lehigh Rd., College Park, MD 20740	46
. "	5008 " "	ii
II .	5012 "	ti
. 11	4908-4914 " "	ll .
П	3838 University Blvd., College Park, MD 20740	78
Commercial	4925 50th Ave., College Park, MD 20740	52
	7410 "	. "
11	7415 " "	11
Commercial	5018 Lakeland Rd., College Park, MD 20740	60

D-21

TYPE	S.TRUCTURE ADDRESS	ELEVATION 1st Floor 100 ye (FT M.S.L.) (FT M.

	:	
	BEAVER DAM	
Residential	2400 Beaver Road, Kent Village, MD 20785 2130 " " " 2120 " "	41
Residential	6401 Country Club Court, Kent Village, MD 20785 6403 "	54
11	6400 "	
u n	6405 " " 6402 " "	11 19
Residential	2707 Country Club Rd., Kent Village, MD 20785	54
 H	2715 " "	11
ii ,	2723	• • • • •
11	2727 " "	**
ii .	2701 "	11 -
Residential	1600 Englewood Ave., Cheverly, MD 20785	31
"	1602 " "	11 ⁻
11	1604 " " 1603 " "	11
11	1605 " "	. 41
Residential	2708 Hawthorne Terrace, Kentland, MD 20785	53
8 . N	2710 " " " " " " " " " " " " " " " " " " "	11
" "	2712	11
	2714 " " 2716 " "	11
11	2718 "	11
11 .	2720 "	11
	2722 " "	
Residential	5314 N. Englewood Dr., Cheverly, MD 20785	33
11	5210 "	32
(1	5212	11
11 -	5214 " " " " " " " " " " " " " " " " " " "	. 11
ir	52.10	. "
u ·	5218 " " 5201 " "	t)
n	5203 " "	ii
n .	5205 "	. 11
	5300	33
# .	5302 " " "	ti 11
H 11	5304 " " 5306 " "	. **
n .	5207 "	32
h	5108 " "	11
11 11	5112 " "	āt

<u>s T</u>	RUCTURE	ELEVA	
TYPE	ADDRESS	lst Floor (FT M.S.L.)	100-yea (FT M.S.L
Residential	2600 Pinebrook Ave., Kentland, MD		54
3) 8i	2602 " "	•	14
 H	2004	•	11
	_ 2000	•	
n ·	2608 " " 2610 " "		U
Residential	1810 61st Ave., Cheverly, MD 20785		35
11	1812 " "		
11	1814 " "		() ()
11	1817 . " "		60
11	1010		. &
18 11	1013		40
	1808 " " 1811 " "		Æ
Residential	1814 62nd Ave., Cheverly, MD 20785	•	37
(1	1812 " "	• •	10
ti	1810 "		16
11	1815 " "		10
II	1813 " "		18,
11	1811 "		11
11 11	1808 " " 1809 " "		9.0 4%
Commercial	8121 Ardwick Ardmore, Rd., Ardwick Industrial P 8201 " "	'ark	75
Commercial .	5800 Columbia Park Rd., Cheverly, MD 20785		41
	5720 " "		40
tţ	5718 "	•	11
ti	5716 "	•	**
Commercial	5700 Columbia Park Rd., Cheverly, MD 20785		35
1f 11	5620 "		II
" "	5618 "		H
II	5610 " .		II.
n	5600 " "		11
	5701 "		ti
Commercial	7229 Country Club Rd., Kentland, MD 20785		54
11	7233 " "		te
K a	7241 " "		18
, ft H	7243 " "		l i
" It	7245 " " " 7249 " " " " " " " " " " " " " " " " " " "	•	n
n ·	/ 4 7 3 '		í ē
	7301		٩٤

<u>S T F</u>	<u>UCTURE</u>		ELEVA	TION
TYPE	ADDRESS		lst Floor (FT M.S.L.)	100-yea (FT M.S.L
Commercial ·	6900 Old Landover Rd., K 6907 " "	entland, MD 20785		55 "
ti	6911 . " "	i.		ti .
11	7000 " "	ı		11
88	7100 "			li .
Commercial "	. 3101 Pennsy Dr., Kentlan 3129 "	d, MD 20785		53
:	3133	-		
17	· 3137 " "	ı		11
H .	3301 " "	J	•	**
	3300 " "	1	_	Ħ

•	STRUC	TURE			1st Floor	100 yea
TYPE		ADDRESS			(FT_M.S.L.)	(FT M.S
			1		•	
		OXON R	<u>UN</u>			
Residential	507 Drum Av 509 511	ve., Capitol	Heights, MD	20027	140 139 142	140 142 142
Residential	2428 2426	Valley Dr.,	11	20023	·	153 155 157
11 11 11 ,	2424 2422 2420	H H	11 11			154

STRUCTURE

ELEVATION
1st Floor 100 yea
(FT M.S.L.) (FT M.S.L.)

TYPE ADDRESS

	·		•
	HENSON CREE	<u>K_</u>	
Residential	4004 Beachcraft Ct., Templ	e Hills, MD 20031	160
. 11	4006 "	** *I	11
" "	4000	· · · · · · · · · · · · · · · · · · ·	!!
11	4014	11	11
11	4010 " 4003 "	"	
11	4003		· 11
•	4005		II
Residential	7102 Bock Rd., Oxon Hill 2	0022	81
•	7104 "	· ·	tt.
Residential	3701 Brinkley Rd., Temple	Hills, MD 20031	121
II .	3504 "	u ·	1) fi
li .	3500 "		•
Residential	2103 Calhoun St., Oxon Hil	1, MD 20022	82
II	2105 "	0	11
	2107 "	11	lt
lt	2109 "	u 🤄	
	2111 "	H .	· u
н	2113	11	ŧī
II	2201 " .	16	n
n , 	2203 "	n	#1
. "	2205 "	11	11
1) }	2207 "	H	. 40
11	2209 "	11	u.
	2211 " 2213 "	u n	
	2213	n ·	. 11
ut	2213	n n	#
 H	2301	n	11
11	2303		. 11
u .	29 00		61
11	2307	n	11
H	2303	ų	11
•	2311 "	•	**
Residential	4304 Canterbury Way-House,	Temple Hills, MD 20031	134
Residential	4609 Eaton Dr., Marlow Hei	ghts. MD 20023	171
. ti	4611 "	"	11
u	4614 "	18	n
II .	4612 "	H .	u
II	4610 "	II .	89
и	4608 "	u	\$1
Residential	4001 Forest Grove Dr., Sui	tland, MD 20023	199
11	4005	11	199
	* *,* *		

<u>S T</u>	RUCTURE	ELEVATION
ТҮРЕ	ADDRESS	lst Floor 100-ye (FT M.S.L.) (FT M.S.
	:	
sidential	4310 Hartford Hills, Suitland, MD 20023 4308 " "	195
19	4306 " -	• ·
esidential	4206 Henderson Rd., Temple Hills, MD 20031	195
	4300 " " " 4302 " "	11
esidential	5400 Henson Dr., Temple Hills, MD 20031	195
sidential	7903 Indian Head Highway, Oxon Hill, MD 20745	N/A
11	7911 " "	
esidential	8420 Indian Head Hwy., Oxon Hill, MD 20022	28
11	8424 . " "	H H
11 10	8426 " "	- 11
	8428 " " " 8430 " " " " " " " " " " " " " " " " " " "	II .
I#	8430 " " " *******************************	н
10	8434 " "	11 11
sidential	5813 Keppler Rd., Temple Hills, MD 20031	•
11	5813 Keppler Rd., Temple Hills, MD 20031 5817 "	158
#	5814 " "	11
11 11	5808 " "	ii
	5806 " " " " " " " " " " " " " " " " " " "	It
ŧI	5811 " " " " " " " " " " " " " " " " " "	H .
11	5805	n
44	5803 " "	11
11	5801 "	II
11 If	5719 " "	H H
II II	5717 " "	· • • • • • • • • • • • • • • • • • • •
	5715 " " " " " " " " " " " " " " " " " " "	u
u	5713 " " " The state of the sta	u ,
II .	5709 " "	
ii .	5707 " "	ıı
и ·	5705 " "	11
	5703 " "	
16 19	5701 " "	if It
	5519 " "	 H
11	5609 " "	16
·	• 5607 " " "	11
	5605 " " " 5603 " " " " " " " " " " " " " " " " " " "	n .
	3003 " "	¥

ST	RUCTURE	ELEVA	T I O N
TYPE	ADDRESS	lst Floor (FT M.S.L.)	100-y (FT M.S
Residential	5920 Ladd Rd., Suitland, MD 20023		160
11	6003		41
II .	5005 " "		H
, II .	6007 " "	•	11
II.	6009 " "		ti .
18	6011 "	ı.	11
Residential	5922 Ladd Rd., Suitland, MD 20023		160
ii	6000 " "		100
ıi .	6002 " "		60
11	6004 " "		11
n	6006 " "		11
	6008 " "		. 11
11	6010 " "		88
ıı	6012 " "		41
11	6014 " "		
u			11
,	0010		
	6018 " "		. #
Residential .	9101 Livingston Rd., Oxon Hill, MD 20022		28
Residential	4901 Meadowbrook Dr., Suitland, MD 20023		175
16 ·	4902 " "		"
Residential	4101 Offut Dr., Suitland, MD 20023	•	175
"	4103 " "		175
	4100 " "		Ð
	4100		•
Residential	5402 Old Temple Hill Rd., Temple Hills, MD 20031		125
11	5400 "		123
II .	5413 " "		Ħ
Iŧ	5411 " "		11
H	5409 "		
II .	5600 " "	•	11
u .	4356 " "		11
Residential	902 Palmer Rd., Oxon Hill, MD 20022		35
			33
Residential	6415 Roberts Dr., Temple Hills, MD 20031		121
ir	6413 "	•	11
· II	6409 " "	.	- 11
19	6405 " "		II .
11	6411 "		*1
II ·	6407 "		II .
. (1	6403 " "		11
Residential	5410 Strafford Lane, Temple Hills, MD 20031		158
II	5410 Strattord Lane, Temple Hiris, Fib. 20051		120
n n	5406 " "		n
	5404 " "	•	B.
ii .	5402 " "		at .
ii	5400 " "		п
. 11	5312 "		11
11	5310 " "		
	JJ (U		

ELEVATION

STRUCTURE

TYPE	ADDRESS	lst Floor (FT M.S.L.)	100-yea (FT M.S.L
Rēsidential "	6206 Suitland Rd., Suitland, MD 20023 6208 " "		195 "
Residential	5515 Temple Hills Rd., Temple Hills, MD 20031	l ⁻ .	134
11	5601 " "		11
u .	5603 "		()
11	5607 "		it
li .	5410 "		IR
11	5412 "		íi
Residential	4300 Weldon Dr., Temple Hills, MD 20031		153
11	4302 " "	•	
	4304		
11	4306))
it 	4308		• 11
() 	4310		14
18	4312	•	-
(1	4314	•	
	4316 " "		41
Residential	501-507 Wilson Bridge Dr., Oxon Hill, MD 20745		и
VE2 I GELLO LO L	509-515 " " " " " " " " " " " " " " " " " "		H
II.	517-523 " "		н
11	525-531 " " "		tt
II.	533-539 " "		11
11	541-547 " "		11
tt.	549-555 " "		H
	557-563 " "		н
	557-563 565 - 573 " ".		n
	202 3/3		

<u>STRL</u>	J C T U R E				ELE	VATION
TYPE		ADDRES	SS		lst Flo (FT M.S	or 100-ye .L.) (FT M.S.
Residential	6211 Woodla	nd Rd., S	Suitland, M	D 20023		175
	0301					11
	6303	H	18	•		11
ii .	6305	10	, I I			ii
Ħ	6307	18	10			ii
	6311	ti	ti			it
11	6401	n	11			ii ii
	6405		u			11
u	6409	, ii	11			II.
и	6411	IF	"			II II
tī .	6415	n t	11			18
11	6417	H	и .			· It
II	6419	H	Ħ	•	•	11
Ħ	6501	41	11			. 15
it	6505	11	**		•	II.
ii .	6509	18	11			16
	6515	11	11			
, 11	6517	н				9
· · · · · · · · · · · · · · · · · · ·	. 6519	u ·	11	•		et
u	6600	n	11	•		11
u	6602	ii .	u ·			ri
10	6604	18	. 11	•		u
10	6606	ti	15	•		ii
n	6608	38 ·	• •			11
n	6610	a	**			**
H	6612	18	H			n
n	6614	18	11			13
11	6616	11	m _			11
U	6618	u				···
n	6620	н		•	•	17
11	00ZU 6633	£†	a			
u ·	6622	11	11		•	
	6700		••			

	STRUCTURE	ELEVA 1st Floor	T I O N 100 yea
TYPE	ADDRESS	(FT M.S.L.)	(FT M.S
Commercial	8500 Indian Head Hwy., Oxon Hill, MD 20022		28
Commercial "	9100 Livingston Rd., Oxon Hill, MD 20022 9116 " " 9011 " " 9001 " "	•	28 "
Commercial	5007 Meadowbrook Dr., Suitland, MD 20023	•	175
Commercial	4625 Old Branch Ave., Temple Hills, MD 20031 4600	·	171
Commercial	6101 Suitland Rd., Suitland, MD 20023 6200 "	•	195 "
Commercial	709 Taylor Acres Ave., Oxon Hill, MD 20022		18

	E10: Of FEOCD FRONT THERE		
· · · · · · · · · · · · · · · · · · ·	STRUCTURE	ELEVA 1st Floor	T I O N 100 yea
TYPE	ADDRESS	(FT M.S.L.)	(FT M.S
	TINKERS CREEK	•	-
Posidontial	FOOT Contribute Dr. Colta. L. ND. COCK	•	Et

					EF
	lridge Dr.	., Suitland, MD	20031		68
	11	n			K
70 07	26	H			11
7003	11	ie .			16
					ŧı
6709 Brar	nch Ave.,	Suitland, MD	20031		11
6711	11	ų			13
					. #
6805 Coo1	lridge Dr.	. Suitland, MD	20031		11
6807	ũ	at .			ti
6809	16	11		÷	ti
	18	H			11
	u	11			ti
	18	II .		•	 11
	ia .	\$1			·
	6907 7007 7003 6709 Brar 6711 6805 Cool	6907 7007 " 7003 " 6709 Branch Ave., 6711 " 6805 Coolridge Dr. 6807 " 6809 " 6811 " 6813 " 6815 "	6907 7007 """ "" 6709 Branch Ave., Suitland, MD 6711 """ 6805 Coolridge Dr., Suitland, MD 6807 """ 6809 """ 6811 """ 6813 """ """ """ """ """ """ """ """ """ "	7007 " " " 7003 " " " 6709 Branch Ave., Suitland, MD 20031 6711 " " 6805 Coolridge Dr., Suitland, MD 20031 6807 " " 6809 " " 6811 " " 6813 " " 6815 " "	6907 7007 """ 7008 """ 6709 Branch Ave., Suitland, MD 20031 6711 """ 6805 Coolridge Dr., Suitland, MD 20031 6807 """ 6809 """ 6811 """ 6813 """ """ 6815 """

STRUCTURE

ELEVATION

st	Floor	100 year
FT	M.S.L.)	(FT M.S.L.

TYPE

ADDRESS

PISCATAWAY

	1.1	JUNITARI	
Residential	11729 Cr	estwood Ave., North Clinton, MD 20613	110
11 11	11737	H	II
'' H	11741	4 1	11
 II	11745	0 11	" H
II	11749 11753		
	11/53		
Residential	3006 Flo	ral Park Rd., Clinton, MD 20613	. 34
II 	3100		11
11	3402	II II	11
II	3410	u, u *	II .
11	3500	H H	11
H H	3611	H H	II
ii	3701	11	li
11	3708	H H H	"
" "	3710	II 41 II	"
n	3711	" " " " " " " " " " " " " " " " " " "	II II
ti .	3805		" "
n .	3806		11
п	4001 4006		
· ·	4006 4020	H H	11
	1020		
Residential	7800 Kno	llwood St., Brandywine, MD 20613	110
It .	7802	II II	11
	7803	п	11
II 	7804	11 11	11
II 	7805	II II	n
II 	7806	H II	. и
1) 1)	7807	II II	11
'' 'I	7808	H	"
" "	7809		11
 II	7810	n n	II .
	7811		H
" "a	7812	en e	II
	7813 7015	и п	II
16	7815 7001	H H	II
	7901		II
Residential	13512 Li	vingston Rd., Accokeek, MD 20022	17
и .	13514	" "	16
H .	13515	п	н
	•		

STRUCTURE

ELEVATION

1st Floor 100-year

TYPE	ADDRESS		(FT M.S.L.)	(FT M.S.L
	PISCATAWAY (cont'd)		
Residential	13516 Livingston	Rd., Accokeek, MD 20022		. 17
п	13600 "	"		. 17
II .	13604 "	ti		0
II .	13606 "	II .		n
II .	13711 "	ti .		II
II	13712 "	u		п
II .	13801 "	11 .		11
11	13809 "	11		11
11	14001 "	н		II
н	13401 Piscataway I	Rd., Clinton, MD 20613		34
н	7600 Padusad Ct	Duran la Cara MD aggra		
н	7600 Redwood Ct.,	Brandywine, MD 20613		118
II	7602 "			11
ti	7603 "			11
н		"		11
н	-7007			н
11	7605 " 7606 "		•	11 11
Residential	11708 Redwood Dr	Brandweine MD 20612		110
ıı .	11712 "	Brandywine, MD 20613		118
u	11713 "	н		n
11	11716 "	н		
11	11717 "	II		н
11	11720 "	II		ti ti
н	11721 "	II .		11
11	11724 "	ii .		ii.
п	11725 "	ti		H
11	11728 "	n .		H
u	11729 "	ti .		u
u	11733 "	II .		H
п	11801 "	П		ti
Residential	3604 Taylor Circle	, Ft. Washington, MD 20022	!	18
н	13001 Winebrook Dr	., Clinton, MD 20735		44
Commercial	11700 Brandywine R	d., Clinton, MD 20613		94

ELEVATION

STRUCTURE

31100	1 0 1/ 12				n.
TYPE	ı	ADDRESS		<pre>lst Floor (FT M.S.L.)</pre>	100-year (FT M.S.L.
T T In	•				
	<u>!</u>	PATUXENT			
Residential	17001 Anna	polis Rd., Anı	napolis, Md. 20715		43
Residential	26 Avondal	e St., Laurel	, Md. 20811	-	148
Residential	12921 Broc	k Bridge Rd.,	Laurel, MD 20811		116
"	12923	.,		•	
II	12925		"		16
!!	12927	"	(I		\$1 15
"	12929	# 			1E 15
() 	12931	1 1	11 14		n n
II 	12909	11			
	12911	(I	11 11		u U
11	12913	" .	11		\$ E
11	12915		" "		
41	12917	() ()	n n		11
II u	12919	 11	,, ,,		,, ,,
11 11	12901	 II	" "		11
	12903		"	•	"
, H H	12905	" II			n
 N	12907	11	 II		ji
	12935		n		
11	12937	 (i	 Ji		
	12939 12941	II	11	•	н
	•				
Residential	23100 Cris	pus Attucks B	lvd., Eagle Harbor,	, MD 20608	7
II	23102		II		11
II 	23106		!!		11
ll 	23110	II 	II		
u	22907	11	II .		li .
Residential	319 Main S	t., Laruel, M	D 20810	•	148
Residential	8400 McClu	re Rd., Upper	Marlboro, MD 20772	2	9
Residential		elier Dr., La	urel, MD 20811		116
• "	9307	ti -	н		н
II 	9309	н	н		Ħ
II 	9306	П	II 		н
II 	9308	H	II		11
11	9310		11		!!
11 11	9312	11	H H		
II.	9314	11	II .		ξį

ELEVATION

STRUCTURE

3 R U C	IUKE			ELEVA	i i U iV
				1st Floor	100-yea
TYPE		ADDRESS		(FT M.S.L.)	(FT M.S.L
		7.001.200		(, , , , , , , , , , , , , , , , , , ,	1
		DATINENT			
		PATUXENT			
D	00000 B		F 7 11 1 15 00 5	••	_
Residential	22803 Pai	ui Sundar Ave.	, Eagle Harbor, MD 206	J8	7
	22900				
II	22907	"	II -		n
#I 	22908	11			11
, II	23001		11		11
u	23003	11	II		II
	23100	н	ш		11
•		•			
<u>.</u>	· · · · · · · · · · · · · · · · · · ·				
Residential	5802 Gree	en Landing Rd.	, Upper Marlboro, MD 20)772	9
"	5902	II	11		ti .
Residential	17400 Riv	ver Airport Rd	., Brandywine, MD 2061:	3	8
					•
Residential	7100 Rout	te 301(NW), An	napolis, MD 20715		43
	7110	"			I)
II .	7]11	. "			1)
	-				
		•			
Commercial	26 Avonda	ale St., Laure	1, MD 20810		148
H	42	•	11		ч
		•	•		
			•		
Commercial			urel, MD_20810		146
# ·	30	II 	II .		11
ii .	42	t i	II		Ħ
	0701 7:				
Commercial	9/01 Ft.	Meade Rd., La	urel, MD_20810		145
	9703				41
ti 	9705	"			4
II	9707	II 	II		
11	9709		II .		tr
	9711	. 11	II .		П
	9713	н	и		11
ii	9715	II 	II		ti .
11 •	9717	II			tj
• ti	9719	II	U		u u
II .	9721	U	II .		ft.
II	9723	II	II .		Ħ
ii .	9725	11	II .		n
п	9727	11	II .		n
H	9729	II	ii		H
H .	9731	, u	II .		н

STRU	CTURE		ELEVATION
TYPE		ADDRESS	lst Floor 100-year (FT M.S.L.) (FT M.S.L.
	<u>!</u>	PATUXENT	
Commercial	1 Main St 9 "	t., Laurel, MD 20810	148 "
II .	19 "	H	. 11
II	21 . "	H .	II
ti .	22 "	tt.	II
H	99 "	II .	n
н	100 "	н	H .
11	101 "	II .	· II
u	103 "	H	·
II	105 "	n	н
11	109 "	II	'u
II	311 "	II	п
11	313 "	II .	, ti
H	315 "	· u	II
11	317 "	II .	11
ii	351 "	II .	II
ll .	353 "	H .	11
11	. 355 "	н	ff.
II	357 "	II	11
11	359 "	H	II
II .	361 "	· u	II .
n '	363 "	11	• "
ti .	365 - "	H	II .
U	367 "	н	u .
II .	369 "	H	II
H .	371 "	II	ti .
IT	373 "	П	н

145

Commercial 1 2nd Ave., Laurel, MD 20810

STRUCTURE

lst Floor 100-year (FT M.S.L.) (FT M.S.L.)

ADDRESS

ТҮРЕ

WESTERN BRANCH BALD HILL

Residential .	6109 C St., Seabrook, MD 20706 6110 "	137
Residential " " "	9213 Lanham Severn Rd., Seabrook, MD 20706 9215 """ 9217 """ 9305 """	13 <u>6</u> " "
Residential "	8810 Magnolia Dr., Seabrook, MD 20706 8811 "	142
Residential "	9103 Sheridan Ct., Seabrook, MD 20706 9104 " " .	137
Residential "	9201 Wellington Ct., Seabrook, MD 20706 9203 "	H H
11 11 11 11	9111 Wellington Pl., Seabrook, MD 20706 9113 " " 9115 " " 9117 " " 9119 " "	11 11 11 11
Residential	9216 3rd St., Seabrook, MD 20706 9217 "- " 9219 " "	11 11
Residential " " " " " "	9219 4th St., Seabrook, MD 20706 9225 " " 9226 " " 9227 " " 9217 5th St., Seabrook, MD 20706	11 11 11 11
11 11	9209 6th St., Seabrook, MD 20706 9212 " " 9214 " "	11 11

	LIST OF FLOO	D PRONE AREAS		
STRUC	TURE		E	LEVATION
TYPE	ADDRESS			Floor 100-year M.S.L.) (FT M.S.L.
	FEDERAL SP	RING		
Residential	13011 Old Marlb 13013 "	oro Pike, Upper	Marlboro, MD 2077	12
II	14003 "	n	11	37
11 11	14005 . "	. u	#	11
	14007 " 14009 "	11	H H	u 11
		•		
Commercial	14011 " 14015 "	H H	H H	ti fi
	14015			
	FOLLY BR	ANCH		
Danidaukia]	10003 D W		WD 0000	
Residential	10321 Buena Vis	ta Ave., Lannan	1, MD 20706	118
• и	10234 Chautauqu 10236 "	a Ave., Lanham,	MD 20706	118
. II II	10236 " 10300 "	11 13	H	H 11
п	·	Lambam MD G	20706	11
	5633 Hiland Ave	., Lailliani, MV 2	.0706	"
Residential	10800 Lanham-Se	vern Rd., Lanha		134
и	10802 " 10804 "	0	H H	#I
н	10805 "	. 11	н	11
Residential	10707 Larch Dr.	Glenn Dale M	ID 20760	124
11	10711 "	II	11 20709	134
п	EESE limaala A	a lambam Ma	20706	***
н	5636 Lincoln Av 5730 "	e., Lannam, MD	20/06 "	118

7401 Northern Ave., Glenn Dale, MD 20769 7409 " " " "

134

STRU	CTURE	ATION
TYPE	ADDRESS lst Floor (FT M.S.L.	100-yea .) (FT M.S.L
	FOLLY BRANCH (cont'd)	
Residential	9902 Poplar St., Lanham, MD 20706	118
u u	9903 " " 9906 " "	 H
Residential "	10706 Potomac St., Glenn Dale, MD 20769 10708 " "	134
п	6507 Woodstream Dr., Lanham, MD 20706	140
Commercial	10802 Lanham-Severn Rd., Lanham, MD 20706 10804 " " "	134
. н	10806 " " " " 7317 Northern Ave., Glenn Dale, MD 20706	H H
	COLLINGTON BRANCH	
Residential	4712 Largo Rd., Upper Marlboro, MD 20772	30
и п	15117 " "	11
" "	15119 " " 15202 " "	32
II	15204 "	11
u u	15206 " " 15208 " "	11 17
Residential	15728 Pointer Ridge Dr., Upper Marlboro, MD 20772	30
u u	15730 " " " 15732 " " " 15734 " " "	11 11
Commercial	6000 Laurel Bowie Rd., Bowie, MD 20716	145

STRUCTU	J R E E L E V	ELEVATION	
ТҮРЕ	lst Floor ADDRESS (FT M.S.L.	100-yea .) (FT M.S.L.	
	TURKEY BRANCH		
Residential	3130 Pyles Dr., Upper Marlboro, MD 20772 3131 " " 3133 " "	82 "	
	2600 Ritchie-Marlboro Rd., Upper Marlboro, MD 20772	108	
	CABIN BRANCH		
Residential	3508 Brown Station Rd., Upper Marlboro, MD 20772	38	
	NORTHEAST		
Commercial	12211 Central Ave., Upper Marlboro, MD 20772	78	
	SOUTHWEST BRANCH		
Residential "	1212 Darlington St., Forestville, MD 20028	148	
Residential	10304 New Orchard Dr., Upper Marlboro, MD 20772	88	
n	2017 Marbury Dr., District Heights, MD 20028	198	
- n n	10402 Rambling Hill Ct., Upper Marlboro, MD 20772 10404 "	83	
Н	1514 Ritchie Rd., Forestville, MD 20028	162	
п	1504 Shady Glenn Dr., District Heights, MD 20027	180	

STRUC	TURE	<u>E L</u>	<u>EVATION</u>
TYPE	ADDRESS	lst F (FT M	loor 100-year 1.S.L.) (FT M.S.L.
	SOUTHWEST BRAI	NCH (cont'd)	
Residential "	11302 Sherrington Ct 11304 "	., Upper Marlboro, MD 20772	72 "
Residential	11102 Webbwood Ct., U	Jpper Marlboro, MD 20772	74
u	11104	11	H
H	11106 " 11108 "		" H
n .	11110 "	II.	 II
н	11112 "	н	н
n .	11174 "	IE	п
11	11105 "	II.	
II	11109 "		п
Residential	11014 Woodlawn Blvd.	, Upper Marlboro, MD 20772	74
Commercial	8617 Central Ave., Ca 9001 "	apitol Heights, MD 20027	120
n .	9001		· 11
11	9003 "	П	
n	9101 "	· ·	n
II .	9171 "	и	11
. "	9175 "	и	п
II .	9179 "	11	11
H	9181 "		ϵ . \mathbf{n}
II	9183 "	n .	H
u	9185 "	n .	H
i i	9195 "	11	II
Commercial	401 Old Ritchie Rd.,	Forestville, MD 20028	128
11	407 "	u "	п
II	408 "	U	II
	•	•	
•	WESTERN (MAIN	STEM)	
Residential	14946 Main St., Upper 14948 "	Marlboro, MD 20772	30
п	15104 "	н	п

STRUCTURE

ELEVATION

SIRUC	IUKE	ELEVA	1 1 0 N
		lst Floor	100-year
TYPE	ADDRESS	(FT M.S.L.)	(FT M.S.L.
	WESTERN BRANCH (MAIN STEM) cont'd)		
	Cartin Stelly contrary		
Residential	15105 W 1 61 W 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
וו	15106 Main St., Upper Marlboro, MD 20772 15108 " "		30
11	15109 " "	•	#I
11	15115 " "		n *
"	15220 " "	,	11
II 	15224 " "		£B.
11 11	15226 " "		. "
11	15241 " "		ſ;
п	15242 " " " 15243 " " " " " " " " " " " " " " " " " " "		11
er e	15243 " " " 15246 " "		' H
n	15247 " "		li
n	15248 " " "		H H
•			
U			
II 11	15100 Peerless Ave., Upper Marlboro, MD 207	72	п
"	15102 " "		11
	15104 " "		fi .
			•
Commercial	11801 Chesterton Dr., Upper Marlboro, MD 207	779	ŧŧ
	The second of th	12	
II	15400 ot		
ii .	15400 Chrysler Dr., Upper Marlboro, MD 20772	<u>}</u>	n ·
II.		•	11
	5200 " Way, "		II
Commenced			
Commercial	5300 Crain Highway, SE, Upper Marlboro, MD 2	:0772	30
II .	5301		
11	5701 Crain Highway, SW, Upper Marlboro, MD 2	.0772	30
II .	5715 " "		н
H .	5717 " "		II
	5719 " "		н . П
ii 	5721 " " "		"
н	5723 " "		 H
H H	5725 " "		n
 H	5727 " " " " " " " " " " " " " " " " " "		u
II	3731		11
11	5/33 " " " " " " " " " " " " " " " " " "		H
	3733 "		1;

STRUCTURE

ELEVATION

1st Floor 100-year (FT M.S.L.) (FT M.S.L.

100-year

ADDRESS TYPE

WESTERN BRANCH (MAIN STEM)

Commercial	5737 Crain Hwy., SW, Upper Marlboro, MD 20772	30
" "	5739 " " " " " " " " " " " " " " " " " " "	11
II	5743 " "	 11
11	. 5745 " "	II.
·~	5747 "	11
11	5749 "	H
и.	5751 " "	11
#I ·	5753 " "	
ti 	5755 "	•11
11 11	5757 " " " " " " " " " " " " " " " " " "	
	3733	11
II .	6000 Crain Hwy., SE, Upper Marlboro, MD 20772 6600 "	30
Commercial	. 5401 Douglas St., Upper Marlboro, MD 20772	11
11	5407 " "	11
u	5405 East Court Dr., Upper Marlboro, MD 20772	30
II.	5409 " "	11
16	5411 " "	11
11	5413 " "	11
11	14741 Gov. Oden Bowie Dr., Upper Marlboro, MD 20772	30
		•
11	14735 Main St., Upper Marlboro, MD 20772	30
II	14940 Main St., Upper Marlboro, MD 20772	i
II .	15004 Marlboro Pike, Upper Marlboro, MD 20772	II
II	15005 "	H
II 	15006 "" "	11
II II	15008 " "	
•11	15011 " " " 15103 " "	11 11
. n	15113 " "	" "
u	" 15113 " " " "	11
	15117	H.
II .	15201 " "	н
II	15203 " "	II.
H ·	15204 " "	11
11 .	15205 " " .	н

STRUCTURE

ELEVATION

ТҮРЕ	ADDRESS	lst F (FT M	loor 100-yea .S.L.) (FT M.S.I
	WESTERN BRANCH	(MAIN STEM)	
Commercial	15207 Marlboro Pike 15209 "	e, Upper Marlboro, MD 20772	30
n n	15209	11	
· H	15213 "	н	11
. н	15222 "	II	п
H	15225 "	11	11
II	15301 " ·	II .	t!
11	15305 "	и	¥1
П	15315 "	II	ii.
II	15055 "		. 11
Commercial	14811 Pratt St., Up 14815 "	per Marlboro, MD 20772	30
Commercial	5404 Water St., Upp 5415 "	er Marlboro, MD 20772	30
	5700 "	u .	11
II.	5408 West Court Dr.	, Upper Marlboro, MD 20772	30

^{*}Some structures contain multi-addresses of commercial or residential uses.

3 6668 14109 4799